



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE #03-03  
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: CS/SMO23000798/Kvp3q2

Date: 22/05/2023

Code: SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBF 4035T	<b>Veh. Inspected</b>	GBK 2650D
<b>Policy No.</b>	D22MTPCVE001775	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2300329/MYE	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	GRACE TEO	<b>Assign Date</b>	26/01/2023

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA HIACE (M)	<b>c.c</b>	2982
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	JTFHT02P100250231	<b>Colour</b>	SILVER
<b>Odometer</b>	136483 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195 R15X8	BRIDGESTONE	9 mm
<b>L/H Front Tyre</b>	195 R15X8	BRIDGESTONE	9 mm
<b>R/H Rear Tyre</b>	195 R15X8	OHTSU	2 mm
<b>L/H Rear Tyre</b>	195 R15X8	OHTSU	2 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/01/2023	<b>Inspection Date</b>	27/01/2023
<b>Survey held at</b>	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**