

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23000805/ANP3M4**Date:** 03/04/2023**REFERENCE**

Insured/Claimant:	HO WEI RUI, GILBERT	Policy No:	1900244032-01	
Date of Loss:	17/01/2023	Nature of Claim:	OD	Claim No: 2244499958SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH6911J		
Make & Model:	AUDI A3 SPORTBACK, 1.0 TFSI S TRONIC (LED) (A)	Engine No:	CHZC33218
Reg. Date:	15/11/2019 (Man. Year: 2019)	Chassis No:	WAUZZZ8VXKA121470
Colour:	Red	Odometer:	27475 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$108,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,684.00	2,012.72	4,671.28	69.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	1,242.00	2,710.00	68.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,636.00	3,254.72	7,381.28	69.40
+ GST 8.00/8.00% (S\$)	850.88	260.38	590.50	69.40
Nett Amount (S\$)	11,486.88	3,515.10	7,971.78	69.40

INSPECTION

Date of Assignment:	27/01/2023		
Date Inspected:	26/01/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,273.00 FS	*1,818.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	207.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	46.00 FS	*36.32 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	190.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	352.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	337.00 FS	*- FS
7	1		*RADIATOR GRILLE	Not Necessary	1,679.00 FS	*- FS
8	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	223.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	222.00 FS	*- FS
10	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
11	1		*CAUTION SIGN STICKER	Not Necessary	17.00 FS	*- FS
12	1		*FRONT WHEEL HOUSING LINER - RH	Torn	198.00 FS	*158.00 FS
13	1		*HEADLIGHT (NPA)	Not Necessary	0.00 FS	*- FS
14	1		*HEADLIGHT LIFT CYLINDER - RH	Not Necessary	165.00 FS	*- FS
15	1		*LIFT CYLINDER HOSE	Not Necessary	81.00 FS	*- FS
16	1		*HORN LOW TONE - RH	Not Necessary	225.00 FS	*- FS
17	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
18	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	6,684.00	2,012.72
-------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,952.00	1,242.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >