2/27/23, 1:12 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI23000806/ANP3Q2

27/02/2023 Date:

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MN000276 **Claimant Vehicle**

SH7012C Insured Vehicle No: SLG2263R No:

Date of Loss: 20/01/2023 Nature of Claim: ΤP Claim No: M2300517

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH7012C

TOYOTA PRIUS TAXI, 1.8 (A) 2ZRR963118 Make & Model: **Engine No:**

Reg. Date: 25/05/2017 (Man. Year: 2017) Chassis No: JTDKB3FU103556797

Colour: Odometer: 643273 km Blue

Engine Capacity: 1798 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Good Yes Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 195/65R15 195/65R15 Rear Tyre Size: Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,602.74	990.32	2,612.42	72.51
Miscellaneous Items		11.00	11.00	0.00	0.00
Labour		2,300.00	1,520.00	780.00	33.91
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	5,913.74	2,521.32	3,392.42	57.37
A	pproved Total (Overridden) (S\$)		2,000.00		
	(S\$)	5,913.74	2,000.00	3,913.74	66.18
	+ GST 8.00/8.00% (S\$)	473.10	160.00	313.10	66.18
	Nett Amount (S\$)	6,386.84	2,160.00	4,226.84	66.18

INSPECTION

26/01/2023 Present Location: Date of Assignment: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 27/01/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: **ADRIAN LING** Manager: **HUEY YON**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Feb 2023)

Parts: TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH7012C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Repair	586.18 FL	*- FL
2	1		*FRT BUMPER CLIPS	Necessary	2.20 FL	*22.00 FL
3	1		*FRT BUMPER SIDE BRACKET LH	Not Necessary	82.30 FL	*- FL
4	1		*FRT FENDER LH	Dented	1,111.93 FL	*1,111.93 FL
5	1		*FRT DOOR ASSY LH	Repair	1,264.00 FL	*- FL
6	1		*FRT WHEEL RIM LH	Not Necessary	1,570.55 FL	*- FL
7	1		*FRT DOOR COMFORT LOGO	Necessary	75.00 F	*75.00 F
8	1		*FRT FENDER EMBLEM LH	Necessary	86.50 FL	*86.50 FL
F=Fra	anchise	part. L=ListIte	mDisc.	-		
				Sub Total (S\$)	4,778.66	1,295.43
			- List Item Discount o	n L Items 25.00/25.00% (S\$)	1,175.92	305.11
				Total Parts (S\$)	3,602.74	990.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		11.00	11.00
	Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,100.00	700.00
2	SPRAYPAINT	New	1,100.00	750.00
3	CHECK WIRING	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
		Gross Labour Cost (S\$)	2,300.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >