

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG23000812/ANCM4**Date:** 08/05/2023**REFERENCE**

Insured/Claimant:	DHARMARAJ RAMESH	Policy No:	2070154137	
Date of Loss:	17/01/2023	Nature of Claim:	OD	Claim No: 5020382187SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX1911E		
Make & Model:	AUDI A7 SPORTBACK, 2.0 TFSI (A)	Engine No:	DLH066891
Reg. Date:	30/10/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF22LN013749
Colour:	White	Odometer:	46900 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$245,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,896.00	5,868.64	6,027.36	50.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,952.00	2,352.00	3,600.00	60.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	17,848.00	8,220.64	9,627.36	53.94
- Excess (\$\$)	1,600.00	1,600.00	0.00	0.00
(\$\$)	16,248.00	6,620.64	9,627.36	59.25
+ GST 8.00/8.00% (\$\$)	1,299.84	529.65	770.19	59.25
Nett Amount (\$\$)	17,547.84	7,150.29	10,397.55	59.25

INSPECTION

Date of Assignment:	27/01/2023		
Date Inspected:	27/01/2023	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	3,677.00 FS	*2,941.60 FS
2	2		*REAR BUMPER FIXING PARTS	Not Necessary	259.00 FS	*- FS
3	2		*REAR BUMPER SECURING STRIP - LH /RH	Not Necessary	102.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Deformed	565.00 FS	*451.60 FS
5	1		*REAR BUMPER CHROME TRIM - CENTER	Cut	261.00 FS	*208.80 FS
6	1		*REAR BUMPER CHROME TRIM - LH	Cracked	265.00 FS	*211.60 FS
7	1		*REAR BUMPER CHROME TRIM	Cracked	688.00 FS	*550.40 FS
8	1		*REAR BUMPER SECURING STRIP	Necessary	204.00 FS	*162.80 FS
9	1		*REAR BOOT LID OPENING CONTROL UNIT	Not Necessary	491.00 FS	*- FS
10	2		*REAR TAILGATE OPENING SENSOR LINE	Not Necessary	460.00 FS	*- FS
11	1		*REAR TELEPHONE AERIAL	Not Necessary	94.00 FS	*- FS
12	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,140.00 FS	*- FS
13	2		*REAR BUMPER IMPACT BAR GASKET - LH / RH	Not Necessary	34.00 FS	*- FS
14	1		*REAR BUMPER GUIDE SECTION - LH UPPER	Not Necessary	54.00 FS	*- FS
15	1		*REAR BUMPER GUIDE SECTION - LH LOWER	Not Necessary	75.00 FS	*- FS
16	1		*REAR BUMPER HOLDING STRAP - CENTER	Not Necessary	140.00 FS	*- FS
17	2		*REAR PARKING AID SENSOR - INNER / OUTER	Not Necessary	598.00 FS	*- FS
18	4		*REAR PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
19	1		*SET REAR BUMPER WIRING	Not Necessary	648.00 FS	*- FS
20	1		*REAR OUTER TAIL LIGHT - LH	Cracked	1,626.00 FS	*1,300.80 FS
21	2		*REAR TAIL LIGHT TRIM - LH	Cracked	104.00 FS	*41.04 FS
22	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	11,896.00 5,868.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING AND LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	600.00
3	TO RESPRAY REAR BUMPER, REAR END PANELLING AND LHS REAR FENDER	New	3,000.00	1,200.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,952.00	2,352.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >