

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT123000813/UQP3E2**Date:** 07/02/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00017352200

**Claimant Vehicle
No :** SKM4101S**Insured Vehicle
No :** SLS6143P

Date of Loss: 19/01/2023

Nature of Claim: TP

Claim
No: SNM23D200603/C02/CHNGPWDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKM4101S**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No: P530210325

Reg. Date: 27/02/2014 (Man. Year: 2013)

Chassis No: JM6BM42A8E0102417

Colour: White

Odometer: 58345 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Falken 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Falken 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,961.74	7,920.40	21,041.34	72.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,450.00	2,610.00	4,840.00	64.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,411.74	10,530.40	25,881.34	71.08
Approved Total (Overridden) (S\$)		8,400.00		
Nett Amount (S\$)	36,411.74	8,400.00	28,011.74	76.93

INSPECTION

Date of Assignment: 27/01/2023

Date Inspected: 27/01/2023 Inspected At:

SPEEDWERKZ PTE LTD (HQ)
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre
Singapore 147807

Estimated Period of Repair: 8.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Feb 2023)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM4101S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,268.00 FL	*1,083.30 FL
2	1		*FRONT BUMPER TOW COVER	Not Necessary	48.20 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	655.30 FL	*541.20 FL
4	2		*FRONT BUMPER SIDE RETAINER	Bent	46.80 FL	*46.80 FL
5	2		*FRONT BUMPER FOG LAMP	Not Necessary	628.00 FL	*- FL
6	2		*FRONT BUMPER MARKER LAMP	Not Necessary	648.00 FL	*- FL
7	1		*FRONT BUMPER AIR GRILLE	Not Necessary	67.60 FL	*- FL
8	2		*FRONT BUMPER HEADLAMP NOZZLE	Not Necessary	588.80 FL	*- FL
9	1		*FRONT BUMPER HEADLAMP NOZZLE COVER	O/S Missing	94.20 FL	*28.50 FL
10	1		*FRONT BUMPER REINFORCEMENT PROTECTOR	Distorted	89.00 FL	*89.00 FL
11	1		*FRONT BONNET	Repair	988.60 FL	*- FL
12	2		*FRONT BONNET HINGES	Not Necessary	112.60 FL	*- FL
13	2		*FRONT BONNET LOCK	Not Necessary	390.40 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	563.60 FL	*- FL
15	1		*FRONT AIRCON CONDENSER	Not Necessary	993.40 FL	*- FL
16	1		*FRONT RADIATOR ASSY	Not Necessary	1,025.40 FL	*- FL
17	1		*FRONT GRILLE	Cracked	586.00 FL	*586.00 FL
18	2		*FRONT GRILLE CHROME MOULDING	Cracked	622.40 FL	*430.00 FL
19	2		*FRONT FENDER	Repair	868.00 FL	*- FL
20	2		*FRONT FENDER INNER SHIELD	Not Necessary	335.40 FL	*- FL
21	2		*FRONT HEADLAMP	Cracked	7,136.00 FL	*2,830.00 FL
22	1		*WIPER WASHER TANK	Not Necessary	92.60 FL	*- FL
23	1		*WIPER WASHER TANK MOTOR	Not Necessary	52.70 FL	*- FL
24	1		*REAR BOOT LID	Dented / Bent	1,642.00 FL	*1,102.30 FL
25	1		*REAR BOOT LOCK	Twisted	465.20 FL	*164.60 FL
26	1		*REAR BOOT LOCK CATCH	Not Necessary	70.20 FL	*- FL
27	2		*REAR BOOT LID HINGES	Not Necessary	336.00 FL	*- FL
28	1		*REAR BOOT INSULATOR	Not Necessary	365.50 FL	*- FL
29	1		*REAR BOOT LID RUBBER	Twisted	315.20 FL	*136.00 FL
30	2		*REAR BOOT COVER LAMP	Not Necessary	1,530.00 FL	*- FL
31	1		*REAR BOOT EMBLEM (MAZDA 3)	Necessary	65.00 FL	*42.00 FL
32	1		*REAR BOOT EMBLEM LOGO	Necessary	72.00 FL	*65.00 FL
33	1		*REAR BOOT EMBLEM (SKYACTIVE)	Necessary	65.00 FL	*60.00 FL
34	2		*REAR TAIL LAMP	Not Necessary	1,970.00 FL	*- FL
35	2		*REAR TAIL LAMP PANEL	Repair	776.00 FL	*- FL
36	1		*REAR END PANEL	Bent	925.00 FL	*435.20 FL
37	1		*REAR END PANEL TOP GARNISH	Twisted	315.50 FL	*162.80 FL
38	1		*REAR SPARE TYRE PANEL	Not Necessary	1,355.00 FL	*- FL
39	1		*REAR SPARE TYRE PANEL TOP COVER BOARD	Not Necessary	475.20 FL	*- FL
40	1		*REAR BUMPER	Distorted	1,421.60 FL	*1,047.30 FL
41	2		*REAR BUMPER SIDE RETAINER	Bent	70.00 FL	*70.00 FL
42	1		*REAR BUMPER REINFORCEMENT	Bent	652.20 FL	*563.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*REAR BUMPER REFLECTOR	Not Necessary	100.00 FL	*- FL
44	2		*REAR BUMPER PLATE LAMP	Not Necessary	170.00 FL	*- FL
45	1		*REAR EXHAUST SILENCER	Not Necessary	1,465.00 FL	*- FL
46	2		*REAR EXHAUST CHROME PIPE	Not Necessary	330.00 FL	*- FL
47	2		*REAR FENDER INNER GARNISH	Not Necessary	1,196.80 FL	*- FL
48	1		*REAR BUMPER TOW COVER	O/S Missing	150.40 FL	*30.00 FL
49	2		*REVERSING SENSOR HOLDER	Not Necessary	88.00 FL	*- FL
50	1		*FRONT & REAR NUMBER PLATE	Front Cracked	90.00 FS	*20.00 FS
51	5		*REAR BOOT INSULATOR CLIPS	Not Necessary	40.00 FS	*- FS
52	3		*END PANEL TOP GARNISH CLIPS	Not Necessary	19.50 FS	*- FS
53	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
54	1		*REAR SPARE TYRE PANEL TOP INSULATOR	Not Necessary	250.00 FS	*- FS
55	5		*REAR BUMPER CLIPS	Necessary	52.00 FS	*40.00 FS
56	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
57	1		*REVERSING CAMERA	Not Necessary	650.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	35,819.30	9,823.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	6,857.56	1,902.60
Total Parts (\$\$)	28,961.74	7,920.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	250.00	20.00
2	TUFF KOTE	New	200.00	60.00
3	REMOVE AND REFIX EXHAUST PIPE	New	180.00	0.00
4	REMOVE AND REFIX RENEW REVERSING SENSOR	New	150.00	50.00
5	REMOVE AND REFIX REAR FENDER INNER TRIM AND GARNISH ETC }	New	150.00	80.00
6	REMOVE AND REFIX CUSHION SEAT, CARPET ETC }	New	250.00	0.00
7	REMOVE AND REFIX RADIATOR & REFILL COOLANT	New	120.00	0.00
8	REMOVE AND REFIX AIRCON CONDENSER & REFILL GAS	New	150.00	0.00
9	TO REMOVE AND REPLACE SPARE PARTS AND PANEL BEATING	New	3,500.00	1,000.00
10	TO SPRAY PAINTING AND ETC	New	2,500.00	1,400.00
Gross Labour Cost (\$\$)			7,450.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >