3/22/23, 11:56 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.

Our File No: CS6/AIS23000815/TVP3E2

79 Robinson Road #09-01 Singapore 068897 **Date:** 22/03/2023

REFERENCE

Insured/Claimant: Mercedes-Benz Singapore Pte. Ltd. (MBS) Policy No: SP2003915046

Date of Loss: 05/01/2023 Nature of Claim: OD Claim No: 202332004604

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNE7040X

 Make & Model:
 MERCEDES-BENZ E300, 2.0 (A)
 Engine No:
 27492032012792

 Reg. Date:
 01/04/2022 (Man. Year: 2022)
 Chassis No:
 W1K2130532B041036

Colour: Silver Odometer: 8945 km

Engine Capacity: 1991 cc

Market Value/New Car

Price: S\$264,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 R19 Rear Tyre Size: 275/35 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------------|------------|------------|------------|--------|
| Parts | | 3,329.08 | 1,401.99 | 1,927.09 | 57.89 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 4,100.00 | 3,060.00 | 1,040.00 | 25.37 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 7,429.08 | 4,461.99 | 2,967.09 | 39.94 |
| | - Excess (S\$) | 700.00 | 700.00 | 0.00 | 0.00 |
| | (S\$) | 6,729.08 | 3,761.99 | 2,967.09 | 44.09 |
| | + GST 8.00/8.00% (S\$) | 538.33 | 300.96 | 237.37 | 44.09 |
| | Nett Amount (S\$) | 7,267.41 | 4,062.95 | 3,204.46 | 44.09 |

INSPECTION

Date Inspected:

Date of Assignment: 27/01/2023

Cycle & Carriage Automotive Pte Ltd (Pandan

27/01/2023 Inspected At: Gardens)

209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Mar 2023)

Parts: M1-COUPE MERCEDES-BENZ E300 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNE7040X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|--------------|---|-------------------|------------|------------|
| 1 | 1 | | *LEFT OUTER REAR LAMP COMBINATION | Cracked | 793.61 FS | *793.61 FS |
| 2 | 1 | | *LEFT INNER REAR LAMP COMBINATION | Cut | 564.36 FS | *564.36 FS |
| 3 | 1 | | *LEFT REAR GASKET FOR LIGHT HOUSING | Necessary | 44.02 FS | *44.02 FS |
| 4 | 1 | | *REAR BUMPER | Repair | 987.75 FS | *-FS |
| 5 | 1 | | *REAR BUMPER LOWER | Not Necessary | 389.53 FS | *- FS |
| 6 | 1 | | *REAR BUMPER LOWER CHROME MOULDING | Not Necessary | 402.10 FS | *-FS |
| 7 | 1 | | *LEFT REAR BUMPER LATERAL SUPPORT | Not Necessary | 89.31 FS | *- FS |
| 8 | 1 | | *LEFT REAR BASIC CARRIER, BUMPER | Not Necessary | 58.40 FS | *- FS |
| F=Fra | anchise | part. S=SpcN | lett. | | | |
| | | | | Total Parts (S\$) | 3,329.08 | 1,401.99 |
| | | | D 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | - | | |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|---|--------------|------------|----------|
| <u>Lab</u> | our Items | | | |
| 1 | PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH | New | 1,200.00 | 960.00 |
| 2 | RESPRAY REAR BUMPER AND BOOTLID | New | 2,400.00 | 1,600.00 |
| 3 | USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS | New | 380.00 | 380.00 |
| 4 | CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE | New | 120.00 | 120.00 |
| | Gross Labou | r Cost (S\$) | 4,100.00 | 3,060.00 |
| | Report was unsubmitted during this | print-out. | | |

< END OF ESTIMATES >