

S. REC BY: Tou Jia REF: CS6/MS23000 815/TVP3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ CD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 8700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 9264K. X

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Turn Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT
Yrk

Date / Time Action / Instruction

Veh No: SNE7040X Yr Regn: 2022 April

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E300 cc 1991

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 8945 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WIK21305326041036

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/5R19

R: W

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PR / SUMI /

TOYO / YOKO, etc

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.L. 27/1/23

Survey held at C&C Pandan Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. insps (\$)

Report Format: _____

Loss Sum / L.B.R. (%)



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNE7040X

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No 62593
Reg No/Reg Date SNE7040X / 01/04/2022
Date In/Mileage / 0
Chassis No W1K2130532B0410369
Engine No 27492032012792
Make/Model MB/E 300 e SEDAN
Colour/Trim 028 859 Mojave Silv/ 042 201 AMG Line Le

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	26/01/2023/ 18:43	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : SP2003915046 // 05/01/2023 DRIVE IN/EXCESS : 26/01/2023 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	960			1200.00
A BPIRES RESpray REAR BUMPER AND LEFT REAR FENDER.	1600			2400.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT		0.10		380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NET				120.00
M LEFT OUTER REAR LAMP COMBINATION	1.00	793.61	00.00	793.61
M LEFT INNER REAR LAMP COMBINATION	1.00	564.36	00.00	564.36
M LEFT REAR GASKET FOR LIGHT HOUSING	1.00	44.02	00.00	44.02
M REAR BUMPER	1.00	987.75	00.00	987.75
M REAR BUMPER LOWER	1.00	389.53	00.00	389.53
M REAR BUMPER LOWER CHROME MOULDING	1.00	402.10	00.00	402.10
M LEFT REAR BUMPER LATERAL SUPPORT	1.00	89.31	00.00	89.31
M LEFT REAR BASIC CARRIER, BUMPER	1.00	58.40	00.00	58.40

Tanjiun 97495749 / 62563561

wp 27/1/23 3:15pm Not Andriable, Renew

5 days & Resurvey new parts Ex \$700

Tanjiun @ theauto.com. Yik Chan Hoe

Confirmed & accepted by

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: ehanhoe.yik@cyclecarriage.com.sg

Nett 7,429.08
8% GST on 7429.08 594.33

Authorized signatory and company stamp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- the body survey is on a visual estimate basis
- No legal document is involved
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Total Payable 8,023.41

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is required at the time of commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383