


4/ Survey



: KAAS/TA6486/8539/TP/11.22
: 8MY 8539A

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		LIST ITEMS:-			
1	1 pc	rear bumper	deformed	\$ 976.00	\$ 976.00
2	1 pc	rear bumper r/h reflector	unconfirmed	\$ 110.00	not affected
3	1 pc	rear bumper l/h side retainer	necessary	\$ 96.00	\$ 96.00
4	1 pc	rear bumper r/h side retainer	necessary	\$ 96.00	\$ 96.00
5	1 set	rear bumper clips	necessary	\$ 35.00	\$ 35.00
6	1 pc	rear end panel	dented	\$ 715.60	repair
7	1 pc	tailgate	buckled	\$ 1,732.10	\$ 1,732.10
8	1 pc	tailgate inner lock	jammed	\$ 452.80	\$ 452.80
9	1 pc	tailgate "noah" chrome garnish	cracked	\$ 767.40	\$ 767.40
10	1 pc	tailgate "hybrid" emblem	necessary	\$ 48.60	\$ 48.60
11	1 pc	tailgate inner trim board	deformed	\$ 769.00	\$ 769.00
12	1 set	tailgate inner trim board clips	necessary	\$ 35.00	\$ 35.00
13	1 pc	tailgate r/h side cowling	broken	\$ 227.00	\$ 227.00
14	2 pcs	tailgate hinges @S\$69.00	bent	\$ 138.00	\$ 138.00
15	1 pc	tailgate weatherstrip	deformed	\$ 360.70	\$ 360.70
16	1 pc	rear windscreen	broken	\$ 1,300.00	\$ 1,300.00
17	1 pc	rear windscreen wiper motor	not working	\$ 553.00	\$ 553.00
18	2 pcs	rear windscreen moulding @S\$48.00	necessary	\$ 96.00	\$ 96.00
19	1 pc	r/h taillamp	broken	\$ 1,236.00	\$ 1,236.00
20	1 pc	l/h taillamp lower filler panel	deformed	\$ 172.00	\$ 472.00
21	1 pc	r/h taillamp lower filler panel	deformed	\$ 172.00	\$ 172.00
22	1 pc	r/h rear fender	buckled	\$ 1,967.00	repair
23	1 pc	r/h rear fender inner trim board	deformed	\$ 756.10	\$ 756.10
24	1 set	r/h rear fender inner trim board clips	necessary	\$ 35.00	\$ 35.00
				\$ 12,846.30	\$ 10,053.70
		Less 25%			\$ 2,513.43
				\$ 12,846.30	\$ 7,540.28
		SPECIAL NETT ITEMS:-			
25	1 set	reverse sensor	not working	\$ 300.00	\$ 250.00
26	1 set	rear view camera	damaged	\$ 480.00	\$ 480.00
27	1 roll	rear windscreen sealant	necessary	\$ 60.00	\$ 40.00
				\$ 840.00	\$ 770.00
			Sub - Total	\$ 13,686.30	\$ 8,310.28

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 13,686.30	\$ 8,310.28
		LABOUR & OTHER CHARGES:			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,600.00	\$ 1,400.00 60
2		To check wiring and rewiring		\$ 60.00	\$ 50.00 30
3		To remove and reinstall tailgate components		\$ 80.00	\$ 60.00 60
4		To remove and reinstall rear windscreen		\$ 150.00	\$ 120.00 120
5		To remove and reinstall rear boot upholstery		\$ 120.00	\$ 100.00 60
6		To remove and reinstall rear quarter glass		\$ 100.00	\$ 80.00 xmn
7		To remove and reinstall reverse sensor		\$ 140.00	\$ 100.00 40
8		To remove and reinstall reverse camera		\$ 150.00	\$ 120.00 40
9		To remove and reinstall rear view camera		\$ 150.00	\$ 120.00 20
10		To apply anti-rust		\$ 100.00	\$ 80.00 50
11		To putty and spray-paint of affected areas		\$ 1,400.00	\$ 1,200.00 800
				\$ 4,050.00	\$ 3,430.00
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
		Sub • Total		\$ 17,736.30	\$ 11,740.28

T = 7310.38
Wf = 1462.07
FT = 5848.31

25850.11

3/2/23