

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS23000826/TVP3M4**Date:** 13/03/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SLM8839J **Insured Vehicle No :** SKW4787K

Date of Loss: 16/01/2023 Nature of Claim: TP Claim No: DMPC2300048H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM8839J**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS034992

Reg. Date: 17/04/2017 (Man. Year: 2017) Chassis No: JTDKB3FU203555349

Colour: Silver Odometer: 435537 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,471.70	2,254.50	3,217.20	58.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,542.00	2,698.00	1,844.00	40.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,013.70</b>	<b>4,952.50</b>	<b>5,061.20</b>	<b>50.54</b>
<b>+ GST 8.00/8.00% (S\$)</b>	<b>801.10</b>	<b>396.20</b>	<b>404.90</b>	<b>50.54</b>
<b>Nett Amount (S\$)</b>	<b>10,814.80</b>	<b>5,348.70</b>	<b>5,466.10</b>	<b>50.54</b>

INSPECTION

Date of Assignment: 27/01/2023

Date Inspected: 27/01/2023 Inspected At: Borneo Motors (S) Pte Ltd (Pandan)  
2 Pandan Crescent  
Singapore 128462

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Mar 2023)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM8839J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
2	1		*SUPPORT, FR BUMPER	Deformed	95.70 FS	*95.70 FS
3	1		*FENDER SUB-ASSY, FR	Bent	1,177.80 FS	*1,177.80 FS
4	1		*LINER, FR FENDER, LH	Torn	243.20 FS	*243.20 FS
5	1		*EMBLEM, SIDE PANEL	Necessary	65.60 FS	*65.60 FS
6	1		*UNIT, HEADLAMP	Not Necessary	3,167.20 FS	*- FS
7	1		*COVER, FR BUMPER	Deformed	622.20 FS	*622.20 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					5,471.70	2,254.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK WIRING AND CONDUCT LEAK TEST	New	198.00	198.00
2	REPL ACC AFF PARTS AND PANEL	New	2,376.00	1,188.00
3	RESPRAY ACC AFF AREA	New	1,968.00	1,312.00
<b>Gross Labour Cost (S\$)</b>			<b>4,542.00</b>	<b>2,698.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >