

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120.00
4	ZZ/001	REPAIR RH FR FENDER & HOOD RENEW FR BUMPER	840.00	560.00
5	ZZ/002	S/PAINT FR BUMPER, RH FR FENDER & HOOD LH FR FENDER(SUPPLE)	800.00	1000.00
6	ZZ/003	RECONDITION AIRCOND & REFILL GAS - SUPPLE <i>A new</i>	240.00	240.00
TOTAL LABOUR CHARGES			2048.00	1968.00

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SGL512T

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 CONDENSER ASSY-SUPPLE ✓ <i>bt</i>	92110-00Q0E			751.10	OK ✓ A
2 LH HEADLAMP-SUPPLE ✓ <i>cm</i>	26060-4EA2A	660.10			OK ✓ A
3 FENDER,ARC-SUPPLE ✓ <i>cm</i>	63810-4EA0A	584.20			OK ✓ A
4 SUNDRIES	NPN			20.00	OK
5 FRT LICENCE PLATE	FLP			60.00	OK
6 BUMPER SET FR	62022-4EA0H	811.30			OK
7 GROMMET(\$2.6X2)	01281-00111			5.20	OK
8 ENERGY ABSORBER	62090-4EA1B	260.40			OK
9 ARMATURE ASSY-F	F2030-4ENMA	898.70			X
10 COVER-BUMPER	622A0-4EA0A	24.90			X
11 GRILLE-RADIATOR	62310-4EA1A	624.50			OK
12 EMBLEM RAD GRIL	62890-4EA0A	86.20			OK
13 LAMP ASSY-RH	26010-4EA2A	660.10			OK
14 CLIP(\$1.4X10)	01553-05933	14.00			OK
SUB TOTAL		3700.80	0.00	836.30	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		740.16	0.00	0.00	
GRAND TOTAL		2960.64	0.00	836.30	
OVERALL TOTAL		3796.94			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED