

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 7434U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED / MTG DISTORTED	709.00	709.00
10	FRONT BUMPER CLIPS @\$3.80	NECESSARY	45.60	45.60
1	FRONT BUMPER CORNER RETAINER RH	DISTORTED	46.00	46.00
1	FRONT BUMPER LOWER LIP	TO REPAIR SEE LABOUR	442.00	-
1	HEADLAMP RH (LED) (TOP HOLDER BROKEN)	MTG BROKEN	2,045.00	1,850.00
1	FRONT FENDER RH	BENT	687.00	580.00
1	FRONT FENDER ARCH PROTECTOR	DENTED	198.00	198.00
20	FRONT FENDER ARCH PROTECTOR CLIPS LH/RH @ \$3.80	NECESSARY	76.00	76.00
1	FRONT FENDER BADGE (HYBRID)	NECESSARY	75.00	75.00
	LESS 20% DISCOUNT		-864.72	-715.92
			3,458.88	2,863.68
	<u>LABOUR</u>			
	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP .		30.00	20.00
	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL.		50.00	30.00
	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FRONT RH DOOR ,DOOR PILLAR ,ROCKER PANEL ,REAR FENDER ARCH PANEL,TRANSFER DOOR FITTING & PART REPLACEMENT.INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER LIP .		600.00	400.00
	TO RESPRAY AFFECTED AREAS (2K-2 TONE).		850.00	500.00
	TO RESEAL PAINT PROTECTION (DIAMONDBRITE CERAMIC) TO SPRAY PAINT AREAS .	NOT NECESSARY	450.00	-
			1,980.00	950.00
	GRAND TOTAL		5,438.88	3,813.68

Report Ref No. CS/SMO23000831/Kwp3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO23000831/Kwp3q2

KONG SENG CHEONG

Licensed Appraiser