

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTERGO Insurance Pte. Ltd.
8 Temasek Boulevard, #04-01 Suntec Tower Three
Singapore 038988**Our File No:** CS/EG123000834/DNP3E2**Date:** 31/03/2023REFERENCE

Insured/Claimant:	TAY JUNJIE	Policy No:	DMPG22013468		
Date of Loss:	24/01/2023	Nature of Claim:	OD	Claim No:	CDMPG23000187

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE9552Y		Engine No:	8ARZ165536
Make & Model:	TOYOTA HARRIER, 2.0 M GRADE (A)		Chassis No:	JTEZB3GH50J004887
Reg. Date:	30/09/2019 (Man. Year: 2019)		Odometer:	48669 km
Colour:	Black			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	S\$130,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,250.00	16,604.00	1,646.00	9.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	1,020.00	600.00	37.04
Paintwork Labour	980.00	600.00	380.00	38.78
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,850.00	18,224.00	2,626.00	12.59
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	20,850.00	17,524.00	3,326.00	15.95
+ GST 8.00/8.00% (S\$)	1,668.00	1,401.92	266.08	15.95
Nett Amount (S\$)	22,518.00	18,925.92	3,592.08	15.95

INSPECTION

Date of Assignment:	27/01/2023	Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	30/01/2023	Inspected At:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	5.0 days		

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Mar 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE9552Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH HEADLAMP (WCP)	Mounting Broken	3,500.00 F	*3,500.00 F
2	1		*LH HEADLAMP (WCP)	Mounting Broken	3,500.00 F	*3,500.00 F
3	1		*RH HEADLAMP SPONGE (WHITE) (WCP)	Cracked	40.00 F	*40.00 F
4	1		*LH HEADLAMP SPONGE (WHITE) (WCP)	Not Necessary	40.00 F	*- F
5	1		*RH HEADLAMP LOWER BRACKET (WCP)	Bent	50.00 F	*50.00 F
6	1		*LH HEADLAMP LOWER BRACKET (WCP)	Not Necessary	50.00 F	*- F
7	1		*FRONT GRILLE (WCP)	Cracked	650.00 F	*650.00 F
8	1		*FRONT GRILLE RH BRACKET (WCP)	Broken	60.00 F	*60.00 F
9	1		*FRONT GRILLE LH BRACKET (WCP)	Broken	60.00 F	*60.00 F
10	1		*FRONT GRILLE EMBLEM (WCP)	Cracked / Mounting Broken	570.00 F	*570.00 F
11	1		*FRONT RADAR WITH BRACKET (WCP)	Broken / Mounting Broken	920.00 F	*920.00 F
12	1		*FRONT BUMPER (WCP)	Torn / Cracked	1,300.00 F	*1,300.00 F
13	1		*FRONT BUMPER CENTER LOWER GRILLE (WCP)	Cut	210.00 F	*210.00 F
14	1		*FRONT BUMPER CENTER LOWER GARNISH (WCP)	Not Necessary	250.00 F	*- F
15	1		*FRONT BUMPER RH FOG LAMP (WCP)	Not Necessary	170.00 F	*- F
16	1		*FRONT BUMPER LH FOG LAMP (WCP)	Not Necessary	170.00 F	*- F
17	1		*FRONT BUMPER RH FOG LAMP BRACKET (WCP)	Not Necessary	90.00 F	*- F
18	1		*FRONT BUMPER LH FOG LAMP BRACKET (WCP)	Not Necessary	90.00 F	*- F
19	1		*FRONT BUMPER LOWER PAD (WCP)	Not Necessary	220.00 F	*- F
20	1		*FRONT BUMPER RH SIDE RETAINER (WCP)	Not Necessary	60.00 F	*- F
21	1		*FRONT BUMPER LH SIDE RETAINER (WCP)	Not Necessary	60.00 F	*- F
22	1		*FRONT BUMPER TOP BEAM (WCP)	Bent	160.00 F	*160.00 F
23	1		*FRONT BUMPER SPONGE (WCP)	Torn	70.00 F	*70.00 F
24	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	280.00 F	*280.00 F
25	10		*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRONT RH FENDER (WCP)	Dented	480.00 F	*480.00 F
27	1		*FRONT RH FENDER INNER SHIELD (WCP)	Not Necessary	240.00 F	*- F
28	10		*FRONT RH FENDER INNER SHIELD CLIPS (WCP)	Not Necessary	20.00 F	*- F
29	1		*FRONT NO.PLATE	Not Necessary	40.00 FS	*- FS
30	1		*FRONT BUMPER PARKING SENSOR	Damaged	280.00 FS	*280.00 FS
Supplementary #1						
31	1		*BONNET CHROME MOULDING (WCP)	Mounting Broken	250.00 F	*250.00 F
32	1		*BONNET LOCK (WCP)	Bent	70.00 F	*70.00 F
33	1		*FRONT SUPPORT PANEL (WCP)	Dented	650.00 F	*650.00 F
34	1		*BRACE PANEL (WCP)	Bent	280.00 F	*280.00 F
35	1		*AIRCON CONDENSER (WCP)	Bent	1,100.00 F	*1,100.00 F
36	1		*INTER COOLER (WCP)	Bent	420.00 F	*420.00 F
37	1		*RADIATOR TOP RH SIDE GUIDE (WCP)	Deformed	50.00 F	*50.00 F
38	1		*RADIATOR TOP LH SIDE GUIDE (WCP)	Deformed	50.00 F	*50.00 F
39	1		*RADIATOR LOWER RH SIDE GUIDE (WCP)	Deformed	50.00 F	*50.00 F
40	1		*RADIATOR LOWER LH SIDE GUIDE (WCP)	Deformed	50.00 F	*50.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	16,620.00	15,120.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,630.00	1,484.00
Total Parts (\$\$)	18,250.00	16,604.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO SPRAY PAINTING	New	980.00	600.00
<u>Labour Items</u>				
2	TO RESET HEADLAMP SYSTEM }	New	280.00	300.00
3	TO RESET RADAR SYSTEM }	New	280.00	0.00
4	TO REPAIR DAMAGES	New	880.00	600.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
5	TO REFILL AIRCON GAS	New	180.00	120.00
Gross Labour Cost (S\$)			2,600.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >