

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI23000835/SVP3Q2**Date:** 16/02/2023REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000812	
Claimant Vehicle No :	SH9110P	Insured Vehicle No :	SMM7884Y	
Date of Loss:	25/01/2023	Nature of Claim:	TP	Claim No: M2300608

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH9110P	Engine No:	D4FDEU493778
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMHU097361
Reg. Date:	29/12/2016 (Man. Year: 2016)	Odometer:	879018 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,083.12	740.40	342.72	31.64
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	650.00	560.00	90.00	13.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,744.12	1,311.40	432.72	24.81
Approved Total (Overridden) (S\$)		1,050.00		
(S\$)	1,744.12	1,050.00	694.12	39.80
+ GST 8.00/8.00% (S\$)	139.53	84.00	55.53	39.80
Nett Amount (S\$)	1,883.65	1,134.00	749.65	39.80

INSPECTION

Date of Assignment:	27/01/2023	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	26/01/2023	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Feb 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH9110P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cut	553.00 FL	*553.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER UNDER MOULDING	Cut	288.00 FL	*288.00 FL
4	1		*REAR BUMPER BEAM	Not Necessary	428.40 FL	*- FL
5	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					1,341.40	913.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					258.28	172.60
Total Parts (\$\$)					1,083.12	740.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	30.00
Gross Labour Cost (\$\$)			650.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >