



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 6656L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE MIRROR ASSY LHS	BROKEN	720.00	720.00
1	SIDE MIRROR COVER LHS	MISSING	260.00	260.00
1	SIDE MIRROR GLASS LHS	CRACKED	250.00	250.00
1	FRONT DOOR LHS	TO REPAIR SEE LABOUR	1,890.00	-
1	FRONT DOOR WINDOW CHROME TRIM LHS	SCRATCHED	250.00	250.00
1	FRONT FENDER LHS	TO REPAIR SEE LABOUR	960.00	-
1	FRONT DOOR RUBBER SEAL LHS	SERVICEABLE	200.00	-
	LESS 10% DISCOUNT		-453.00	-148.00
			4,077.00	1,332.00
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR LHS AND FRONT FENDER LHS.		800.00	250.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		800.00	300.00
	TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS.		100.00	20.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-
	DIAGNOSTIC CHECK.		100.00	60.00
	TRANSFER DOOR PARTS.	NOT NECESSARY	150.00	-
			2,050.00	630.00
	GRAND TOTAL		6,127.00	1,962.00

RECOMMENDED COST OF REPAIRS			1,962.00
------------------------------------	--	--	-----------------

Report Ref No. CS/FCI23000836/Knp3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.