



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23000836/Knp3e2 Date: 03/05/2023  Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SG 6315R	Veh. Inspected	SNC 6656L
Policy No.		Coverage (\$)	0.00
Claim No.	D23000333MFBP	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	27/01/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MERCEDES BENZ GLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WDC1569422J655097	Colour	METALLIC GREY
Odometer	53084 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/50 R18	MICHELIN	8 mm
L/H Front Tyre	235/50 R18	MICHELIN	8 mm
R/H Rear Tyre	235/50 R18	MICHELIN	8 mm
L/H Rear Tyre	235/50 R18	MICHELIN	8 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	19/01/2023	Inspection Date	21/02/2023
Survey held at	CAR TIMES AUTOLUTION PTE LTD 13 KAKI BUKIT ROAD 4 #03-29/30 BARTLEY BIZ CENTRE SINGAPORE 417807		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	