

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000840/UYA3Q2**Date:** 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900119425
Claimant Vehicle No :	SMF6563S	Insured Vehicle No :	SMM7909K
Date of Loss:	25/01/2023	Nature of Claim:	TP
		Claim No:	3533201243SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF6563S	Engine No:	L15B5670663
Make & Model:	HONDA HR-V, 1.5 LX CVT (A)	Chassis No:	JHMRU1830JX200662
Reg. Date:	20/11/2018 (Man. Year: 2018)	Odometer:	65644 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,931.60	3,756.32	14,175.28	79.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	1,890.00	2,290.00	54.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,111.60	5,646.32	16,465.28	74.46
Approved Total (Overridden) (\$\$)		4,500.00		
(\$\$)	22,111.60	4,500.00	17,611.60	79.65
+ GST 8.00/8.00% (\$\$)	1,768.93	360.00	1,408.93	79.65
Nett Amount (\$\$)	23,880.53	4,860.00	19,020.53	79.65
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,262.00		

INSPECTION

Date of Assignment:	26/01/2023	
Date Inspected:	26/01/2023	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	110.20 F	*110.20 FL
2	1		*TAILGATE	Dented	1,099.20 F	*915.90 FL
3	1		*TAILGATE HR-V EMBLEM	Necessary	66.80 F	*48.00 FL
4	1		*TAILGATE I-VTEC EMBLEM	Necessary	85.00 F	*45.00 FL
5	1		*TAILGATE HYBRID EMBLEM	Not fitted	88.00 F	*- FL
6	1		*TAILGATE H LOGO	Not Necessary	45.00 F	*- FL
7	1		*TAILGATE OUTER HANDLE GARNISH	Not Necessary	450.00 F	*- FL
8	2		*TAILGATE REFLECTORS	Not Necessary	772.40 F	*- FL
9	1		*TAILGATE INNER LOCK	Bent / Twisted	199.80 F	*174.70 FL
10	1		*TAILGATE LOCK STRIKER	Not Necessary	66.00 F	*- FL
11	1		*TAILGATE INNER TRIM BOARD	Deformed / Torn	435.00 F	*435.00 FL
12	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
13	1		*TAILGATE WEATHERSTRIP	Twisted	288.00 F	*105.60 FL
14	1		*REAR BUMPER	Dented	980.00 F	*484.70 FL
15	2		*REAR BUMPER SIDES	Not Necessary	470.20 F	*- FL
16	1		*REAR BUMPER REFLECTORS	N/S Cracked	302.00 F	*151.00 FL
17	1		*REAR BUMPER UNDER COVER	Twisted	541.00 F	*321.00 FL
18	1		*SET REAR BUMPER UNDER COVER CLIPS	Necessary	50.00 F	*30.00 FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
20	1		*REAR END PANEL	Dented	665.20 F	*399.40 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	341.10 F	*208.60 FL
22	2		*TAILLAMPS	Not Necessary	1,300.00 F	*- FL
23	2		*TAILLAMP HOUSING PANELS	Repair	700.00 F	*- FL
24	1		*REAR BUZZLE SENSOR	Cracked	98.00 F	*98.00 FL
25	2		*REAR FENDERS	Repair	2,180.00 F	*- FL
26	1		*REAR FENDER OUTER PROTECTORS	N/S Torn	760.00 F	*280.80 FL
27	1		*REAR FENDER UNDER SHIELD N/S	Not Necessary	288.50 F	*- FL
28	1		*REAR FENDER INNER TRIM BOARDS	N/S Twisted	790.00 F	*395.00 FL
29	1		*REAR FLOOR PANEL	Repair	1,280.00 F	*- FL
30	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	522.00 F	*- FL
31	1		*REAR FLOOR PANEL TOP TRAY	Not Necessary	585.00 F	*- FL
32	1		*REAR FLOOR INNER N/S PANEL	Not Necessary	355.20 F	*- FL
33	1		*REAR EXHAUST	Not Necessary	765.00 F	*- FL
34	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	108.00 F	*- FL
35	1		*REAR AIR VENT N/S	Not Necessary	45.00 F	*- FL
36	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
37	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
39	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
40	1		*SET REAR REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
41	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	120.00 FS	*- FS
					Sub Total (\$\$)	17,931.60 4,612.90
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 856.58
					Total Parts (\$\$)	17,931.60 3,756.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	180.00	0.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
8	TO SPRAY RUST PROOFING	New	100.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (\$\$)			4,180.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >