

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000842/UYA3Q2**Date:** 17/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000001099
Claimant Vehicle No :	SMQ8868S	Insured Vehicle No :	SMS2311K
Date of Loss:	23/01/2023	Nature of Claim:	TP
		Claim No:	1037827998SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ8868S		
Make & Model:	TOYOTA LEXUS, 2.5 ES250 4DR SEDAN (AUTO) EXECUTIVE (A)	Engine No:	A25A0511645
Reg. Date:	25/11/2019 (Man. Year: 2019)	Chassis No:	JTHB11B1002020141
Colour:	White	Odometer:	52316 km
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,826.08	2,548.17	6,277.91	71.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	850.00	2,390.00	73.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,066.08	3,398.17	8,667.91	71.84
Approved Total (Overridden) (\$\$)		2,700.00		
Nett Amount (\$\$)	12,066.08	2,700.00	9,366.08	77.62
+ Car Rental (5.0 x S\$150.00/day) (\$\$)		750.00		
+ Doc/Search Fee (\$\$)		33.00		
Nett Liability (\$\$)		3,483.00		

INSPECTION

Date of Assignment:	26/01/2023	Zoom Autowerks Pte Ltd (HQ)
Date Inspected:	26/01/2023 Inspected At:	130 Bedok Reservoir Road, Eunost Spring, #08-1339
Estimated Period of Repair:	3.0 days	Singapore 470130

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Not Necessary	1,889.75 FN	*- FN
2	1		*REAR BOOT LID INNER LOCK	Not Necessary	345.00 FN	*- FN
3	1		*REAR BOOT LOGO	Not Necessary	108.00 FN	*- FN
4	1		*REAR BOOT RUBBER	Not Necessary	233.96 FN	*- FN
5	1		*REAR BOOT LEXUS EMBLEM	Not Necessary	120.33 FN	*- FN
6	1		*REAR BOOT ES250 EMBLEM	Not Necessary	100.30 FN	*- FN
7	2		*REAR TAILLAMPS	Not Necessary	1,401.50 FN	*- FN
8	1		*REAR END PANEL	Repair	800.17 FN	*- FN
9	1		*REAR END PANEL INNER GARNISH	Not Necessary	188.95 FN	*- FN
10	1		*REAR END PANEL INNER SENSOR	Not Necessary	195.20 FN	*- FN
11	1		*REAR BUMPER	Deformed / Torn	999.40 FN	*999.40 FN
12	1		*REAR BUMPER INNER SPONGE	Torn	139.50 FN	*139.50 FN
13	2		*REAR BUMPER REFLECTORS	Not Necessary	220.60 FN	*- FN
14	1		*REAR BUMPER REINFORCEMENT	Bent	689.50 FN	*689.50 FN
15	2		*REAR BUMPER SIDE BRACKETS	Not Necessary	160.34 FN	*- FN
16	1		*REAR BUMPER SIDE RETAINERS	N/S Bent	140.34 FN	*70.00 FN
17	1		*REAR BUMPER PDC SENSOR (4 PCS)	Shorted (1 PCS ONLY)	1,067.00 FN	*266.75 FN
18	1		*REAR BUMPER SIDE CHROME MOULDINGS	N/S Cracked	570.40 FN	*285.20 FN
19	1		*REAR BUMPER CENTRE (LOWER GARNISH)	Grazed	325.40 FN	*325.40 FN
20	1		*SET REAR BUMPER CLIP	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	9,795.64	2,825.75
- Nett Item Discount on N Items 10.00/10.00% (\$)	969.56	277.58
Total Parts (\$)	8,826.08	2,548.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE DAMAGED LAMPS & CHECK UP WIRING	New	80.00	20.00
2	TO REMOVE & REFIT INNER GARNISHES	New	180.00	0.00
3	TO REMOVE & REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	80.00	0.00
5	TO APPLY UNDERCOATING	New	150.00	0.00
6	PANEL BEATING	New	1,400.00	380.00
7	TO RE-SPRAY THE AFFECTED AREAS	New	1,200.00	400.00
Gross Labour Cost (S\$)			3,240.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >