

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000843/UYA3Q2**Date:** 14/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100412943
Claimant Vehicle No :	SGR4L	Insured Vehicle No :	SFW3225G
Date of Loss:	21/01/2023	Nature of Claim:	TP
		Claim No:	2746784834SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGR4L	Engine No:	L15B6020510
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK82100424
Reg. Date:	16/11/2021 (Man. Year: 2019)	Odometer:	89310 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,028.08	2,521.68	7,506.40	74.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	1,160.00	2,050.00	63.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,238.08	3,681.68	9,556.40	72.19
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	13,238.08	2,900.00	10,338.08	78.09
+ GST 8.00/8.00% (S\$)	1,059.05	232.00	827.05	78.09
Nett Amount (S\$)	14,297.13	3,132.00	11,165.13	78.09
+ Car Rental (3.0 x S\$100.00/day + 8.00% GST) (S\$)		324.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,458.00		

INSPECTION

Date of Assignment:	27/01/2023		
Date Inspected:	27/01/2023	Inspected At:	TLM Automobile Pte Ltd 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,193.40 FL	*1,193.40 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	383.40 FL	*110.00 FL
3	1		*TAILGATE EMBLEM H	Necessary	55.10 FL	*55.10 FL
4	1		*TAILGATE EMBLEM SHUTTLE	Necessary	48.30 FL	*48.30 FL
5	1		*REAR TAILGATE EMBLEM ODYSSEY	No such part	51.50 FL	*- FL
6	2		*REAR TAILGATE REFLECTOR LAMP	Not Necessary	900.00 FL	*- FL
7	2		*REAR TAILGATE NO PLATE LAMP	Not Necessary	90.00 FL	*- FL
8	1		*REAR TAILGATE WIPER MOTOR	Not Necessary	320.40 FL	*- FL
9	1		*REAR TAILGATE LOCK	Not Necessary	120.40 FL	*- FL
10	1		*REAR TAILGATE TRIMBOARD	Cracked	201.40 FL	*201.40 FL
11	1		*REAR TAILGATE INNER HANDLE	Not Necessary	35.40 FL	*- FL
12	2		*REAR TAILGATE STOPPER	Not Necessary	50.00 FL	*- FL
13	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	117.30 FL	*- FL
14	1		*REAR TAILGATE LOWER CHROME	Scratched	295.00 FL	*295.00 FL
15	2		*REAR TAIL LAMP	Not Necessary	1,670.00 FL	*- FL
16	1		*REAR BUMPER	Dented	911.40 FL	*911.40 FL
17	2		*REAR BUMPER SIDE COVER	Not Necessary	190.00 FL	*- FL
18	2		*REAR BUMPER SIDE COVER RETAINER	Not Necessary	130.00 FL	*- FL
19	2		*REAR BUMPER SIDE RETAINER	Not Necessary	150.00 FL	*- FL
20	2		*REAR BUMPER REFLECTOR	Not Necessary	190.00 FL	*- FL
21	1		*END PANEL	Repair	560.40 FL	*- FL
22	1		*END PANEL TOP GARNISH	Not Necessary	121.80 FL	*- FL
23	1		*SPARE TYRE PANEL	Not Necessary	983.80 FL	*- FL
24	1		*SPARE TYRE TOP BOARDS	Not Necessary	401.70 FL	*- FL
25	2		*REAR FENDER INNER TRIMBOARD	Not Necessary	1,960.00 FL	*- FL
26	1		*REVERSE CAMERA	Not Necessary	81.90 FL	*- FL
27	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	344.10 FL	*- FL
28	1		*KEYLESS SENSOR	Not Necessary	78.40 FL	*- FL
29	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	450.00 FS	*200.00 FS
30	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
31	1		*REAR NUMBER PLATE	Not Necessary	60.00 FS	*- FS
32	10		*TAILGATE TRIMBOARD CLIPS	Not Necessary	60.00 FS	*- FS
33	1		*TUBE TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,355.10	3,084.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,327.02	562.92
Total Parts (\$\$)	10,028.08	2,521.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,200.00	380.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	500.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	200.00	30.00
4	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATER SEEPAGE TEST	New	100.00	60.00
5	TO REPLACE REAR PARKING SENSOR	New	80.00	50.00
6	TO REMOVE AND REFIX REAR UPHOLSTERY ASSY ,INNER TRIM BOARDS AND REAR SEATS ASSY	New	200.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
8	TO REMOVE AND REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
Gross Labour Cost (S\$)			3,210.00	1,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >