

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000874/UPA3Q2**Date:** 19/02/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210027647
Claimant Vehicle No :	FX9274U	Insured Vehicle No :	SKB1330A
Date of Loss:	23/01/2023	Nature of Claim:	TP
		Claim No:	0243871994SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FX9274U	Engine No:	NF125MSE0005789
Make & Model:	HONDA WAVE 125, 125cc	Chassis No:	NF125MS0005789
Reg. Date:	06/04/2004 (Man. Year: 2004)	Odometer:	91947 km
Colour:	Red		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	90/80-17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,745.00	626.20	2,118.80	77.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	745.00	315.00	430.00	57.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,490.00	941.20	2,548.80	73.03
Approved Total (Overridden) (\$\$)		750.00		
Nett Amount (\$\$)	3,490.00	750.00	2,740.00	78.51
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	30/01/2023		
Date Inspected:	30/01/2023	Inspected At:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4 Singapore 539410
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE WHEEL FRONT	Cut	28.00 F	*28.00 FL
2	1		*BAR HANDLE	Bent	42.00 F	*42.00 FL
3	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Cut	239.00 FS	*160.00 FS
4	1		*BRACKET UNDER FORK	Serviceable	262.00 F	*- FL
5	1		*CALIPER BRAKE FRONT ASSY	Serviceable	190.00 F	*- FL
6	1		*COVER BODY	Cracked	90.00 F	*90.00 FL
7	1		*COVER FRONT UPPER	Repair	45.00 F	*- FL
8	1		*COVER LEG SHIELD INNER RH	Cut	21.00 F	*21.00 FL
9	1		*COVER WINDSHIELD LOWER	Repair	72.00 F	*- FL
10	1		*COWLING FRONT ASSY	Cut	45.00 F	*45.00 FL
11	1		*FOOTREST FRONT	Torn	35.00 F	*35.00 FL
12	1		*FORK FRONT ASSY LH	Serviceable	259.00 F	*- FL
13	1		*FORK FRONT ASSY RH	Serviceable	259.00 F	*- FL
14	1		*GRIP HANDLE LEFT	Torn	21.00 F	*21.00 FL
15	1		*GRIP HANDLE SET (HMA) RH & LH	Necessary	16.00 F	*16.00 FL
16	1		*HEADLAMP	Scratched	50.00 F	*50.00 FL
17	1		*LAMP SIGNAL FRONT LH	Not Necessary	25.00 F	*- FL
18	1		*LAMP SIGNAL FRONT RH	Not Necessary	25.00 F	*- FL
19	1		*LEVER BRAKE	Broken	20.00 F	*20.00 FL
20	1		*MIRROR RH	Cut	28.00 F	*28.00 FL
21	1		*MUDGUARD FRONT (RED)	Cut	68.00 F	*68.00 FL
22	1		*MUFFLER ASSY	*Check	620.00 F	*- FL
23	1		*PEDAL BRAKE	Bent	45.00 F	*45.00 FL
24	1		*RUBBER FOOTREST FRONT	Torn	9.00 F	*9.00 FL
25	1		*SHAFT MAINSTAND	Not Necessary	18.00 F	*- FL
26	1		*SHOCK ABSORBER REAR YSS	Not Necessary	143.00 F	*- FL
27	1		*SET STEERING CONE	Not Necessary	70.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,745.00	678.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	51.80
Total Parts (S\$)	2,745.00	626.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT CHARGES	New	65.00	35.00
2	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	680.00	280.00
Gross Labour Cost (S\$)			745.00	315.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >