



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 6004T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	BENT	595.00	595.00
1	REAR BUMPER REINFORCEMENT (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR END PANEL (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-59.50	-59.50
			535.50	535.50
	<u>SPECIAL NETT ITEMS</u>			
1	SET BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR PARKING SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
			235.00	235.00
	<u>LABOUR</u>			
	TO REMOVE ALL DAMAGED PARTS, KNOCK OUT DENTS, JACK OUT DAMAGED PANEL, ADJUST, REPLACE, RESHAPE, CUT, WELD, REFIX & REALIGN BODY STRUCTURE. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT AND REAR END PANEL.		450.00	200.00
	SPRAY PAINTING FOR NEW AND REPAIR PARTS INCLUDING SUPPLY OF PAINTS MATERIALS.		600.00	200.00
	TO CHECK WIRING FOR PROPER FUNCTION.		50.00	15.00
			1,100.00	415.00
	GRAND TOTAL		1,870.50	1,185.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			850.00

Report Ref No. CS/ASM23000875/Kwp3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.