



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: OH VALE			Ref: CS/ASM23000875/Kwp3e2 Date: 22/02/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 2344U	Veh. Inspected	SKX 6004T	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S3M04IIU	Excess (\$)	0.00	
Assign From	OH VALE	Assign Date	30/01/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA WISH (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDGG20W60J003442	Colour	METALLIC GREY	
Odometer	142573 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	8 mm	
L/H Front Tyre	195/65 R15	MICHELIN	8 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	8 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	20/01/2023	Inspection Date	02/02/2023	
Survey held at	READY AUTO CARE PL BLK 10 #03-06, AMK AUTOPOINT, ANG MO KIO AVE 5, INDUSTRIAL PARK 2A, SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		