

ASS. REC. BY:

REF:

CS/SMR 23000881/Dny³

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 7/p % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: EGM 518 Yr Regn: Nov 12017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen DS5 c.c. 1560

Colour: Gray A/C: Insured / Std / NI / NA

Sp. Reading: 122323 T/Radio: Insured / Std / NI / NA

Eng/No: 10JBH1X3004951

C/No: VF7KFB4ZTG8505028

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapsen

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 26/01/2023 D.O.I. 31/01/2023

Survey held at CS ong AHK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SMR 8HB 1329R

22/02/23

price 7/p 12.10.82 - with 2 day. 7 day
2/5 1,000/-

(Red. \$ 43308.37, 98%)

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair: 2

1) 23/2/23

☐

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

Survey Fee:

Transportation:

3 + RS \$1

Photos

Others

Report Format: TP

1000

C. S. ONG AUTO PTE LTD

10, ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT, SINGAPORE 568047

TEL: 6484 1933 | FAX: 6484 1922

E-Mail: csongauto@yahoo.com.sg

To: MS FIRST CAPITAL

Att: Motor Claims Dept

ESTIMATED REPAIR COSTS FOR SGM51B

MODEL : CITROEN DS5

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	FRONT DOOR RH	\$ 2,830.00	X
1PC	FRONT DOOR WINDOW MOULDING RH	\$ 240.00	X
1PC	FRONT DOOR LOCK RH	\$ 452.10	X
1PC	FRONT DOOR WEATHER STRIP INNER RH	\$ 499.00	X
1PC	FRONT DOOR WEATHER STRIP OUTER RH	\$ 495.00	X
1PC	FRONT DOOR INNER TRIM BOARD RH	\$ 1,701.00	X
1PC	FRONT DOOR CHROME MOULDING RH	\$ 638.00	X
1PC	FRONT DOOR REGULATOR RH	\$ 872.00	X
1PC	FRONT DOOR REGULATOR MOTOR RH	\$ 983.00	X
1PC	REAR DOOR RH	\$ 2,830.00	X
1PC	REAR DOOR WINDOW MOULDING RH	\$ 240.00	X
1PC	REAR DOOR LOCK RH	\$ 452.10	X
1PC	REAR DOOR WEATHER STRIP INNER RH	\$ 499.00	X
1PC	REAR DOOR WEATHER STRIP OUTER RH	\$ 495.00	X
1PC	REAR DOOR INNER TRIM BOARD RH	\$ 1,701.00	X
1PC	REAR DOOR CHROME MOULDING RH	\$ 638.00	X
1PC	REAR DOOR REGULATOR RH	\$ 872.00	X
1PC	REAR DOOR REGULATOR MOTOR RH	\$ 983.00	X
1PC	SIDE SKIRT RH	\$ 1,618.00	X
1PC	ROCKER PANEL RH	\$ 1,692.00	X
1PC	REAR FENDER RH	\$ 4,302.14	X
1PC	REAR FENDER GLASS WITH MOULDING RH	\$ 1,662.00	X
1PC	REAR FENDER INNER RH	\$ 2,870.00	X
1PC	REAR FENDER INNER SHIELD RH	\$ 375.00	X
1PC	REAR FENDER INNER TRIM RH	\$ 1,140.00	X
1PC	REAR WHEEL BEARING RH <i>Dam</i>	\$ 412.00	X
1PC	REAR WHEEL BEARING HUB RH	\$ 492.00	X
1PC	REAR KNUCKLE ARM RH	\$ 1,102.20	X
1PC	REAR LOWER ARM RH <i>HH</i>	\$ 699.00	X
1PC	REAR THRUST ARM RH	\$ 601.00	X
1PC	REAR ABSORBER RH	\$ 705.00	X
1PC	REAR UPPER ARM RH	\$ 528.00	X

1PC	REAR BUMPER	3 HH	\$ 1,945.20	X
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$195.00 EACH		\$ 390.00	X

412.00

370.80 =

PARTS SUM: \$ 37,953.74
 PARTS LESS 10%: \$ 3,795.37
 PARTS TOTAL: \$ 34,158.37

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1PC SPORT RIM CWT		\$ 1,800.00	500/-
*	TO SUPPLY 1PC TYRE		\$ 600.00	X
*	TO SUPPLY FRONT DOOR INNER TRIM CLIPS		\$ 50.00	X
*	TO SUPPLY SIDE SKIRT CLIPS		\$ 50.00	X
*	TO SUPPLY ROCKER PANEL SEALANT		\$ 80.00	X
*	TO SUPPLY REAR FENDER SEALANT		\$ 80.00	X
*	TO SUPPLY REAR FENDER GLASS SEALANT		\$ 80.00	X
*	TO SUPPLY REAR FENDER GLASS DAMPING SEAL		\$ 60.00	X
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS		\$ 80.00	X
*	TO SUPPLY REAR FENDER INNER SHIELD CLIPS		\$ 50.00	X
*	TO SUPPLY REAR BUMPER CLIPS		\$ 50.00	X
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS		\$ 300.00	HH
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS		\$ 2,000.00	200/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS		\$ 2,000.00	HH
*	TO TUFF COAT DAMAGED AREAS		\$ 300.00	HH
*	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS		\$ 400.00	80/-
*	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT		\$ 120.00	60/-
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS		\$ 250.00	HH
*	TO RNR REAR DOOR MECHANISM TO FACILITATE REPAIRS		\$ 250.00	HH
*	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS		\$ 150.00	HH
*	TO RNR REAR FENDER WINDOW TO FACILITATE REPAIRS		\$ 300.00	HH
*	TO RNR CABRIOLET ROOF TO FACILITATE REPAIRS		\$ 600.00	HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS		\$ 200.00	HH
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS		\$ 300.00	HH

LABOUR & S/N TOTAL: \$ 10,150.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 44,308.37

~~2/1~~ 1,210.80

2/5 1,000/-

31/01/2023 @ 1035hrs

Not Actual

2/5 sum 2 days


Yan

Check damage consistency

2KK Auto

Check part prices.



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: