

LKK Auto Consultants Pte Ltd

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1325Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (N)	TO REPAIR SEE LABOUR	1,075.00	-
1	REAR BUMPER CENTRE CLIPS (N)	NOT NECESSARY	12.50	-
1	REAR BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	558.00	-
2	REAR BUMPER SIDE RETAINER @\$92.00 (N)	NOT NECESSARY	184.00	-
2	REAR BUMPER SIDE HOLDER @\$74.00 (N)	NOT NECESSARY	148.00	-
4	REAR BUMPER SIDE HOLDER RIVET @\$6.00 (N)	NOT NECESSARY	24.00	-
2	REAR BUMPER REFLECTOR @\$55.00 (N)	NOT NECESSARY	110.00	-
2	REAR BUMPER SCREW @\$9.00 (N)	NOT NECESSARY	18.00	-
1	REAR BUMPER SCREW SPACER (N)	NOT NECESSARY	10.00	-
2	REAR BUMPER TOW COVER @\$18.00 (N)	NOT NECESSARY	36.00	-
	LESS 20% DISCOUNT		-435.10	-
			1,740.40	-
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PARKING SENSOR (SN)	NOT NECESSARY	450.00	-
1	REAR BUMPER LOWER SKIRTING (SN)	TO REPAIR SEE LABOUR	800.00	-
			1,250.00	-
	<u>LABOUR</u>			
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR BUMPER REINFORCEMENT AND REAR BUMPER LOWER SKIRTING.		600.00	100.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		500.00	400.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	NOT NECESSARY	80.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	80.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	80.00	-
			1,340.00	500.00
	GRAND TOTAL		4,330.40	500.00

Report Ref No. CS/AGI23000884/Uqy3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		500.00	
-----------------------------	--	--------	--

Report Ref No. CS/AGI23000884/Uqy3e2

CHUA KANG SENG Licensed Appraiser