



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 7045B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	589.50	589.50
1	REAR BUMPER END SEAL COVER RH	DEFORMED	58.50	58.50
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	423.90	-
1	REAR BUMPER RH REFLECTOR	CRACKED	63.40	63.40
2	REAR BUMPER SIDE RETAINER L/R @\$116.00	O/S DAMAGED	232.00	45.00
1	REAR RH FENDER	DENTED	1,218.20	1,218.20
1	REAR RH TAILLAMP	CRACKED	402.80	402.80
1	REAR RH TAILLAMP LOWER BRACKET	CRACKED	64.00	64.00
	LESS 25% DISCOUNT		-763.08	-610.35
			2,289.22	1,831.05
1	REAR RH SPORT RIM (SN)	CUT	2,133.00	800.00
	LESS 25% DISCOUNT		-533.25	-
			1,599.75	800.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR RH TAILLAMP CLIPS (SN)	NECESSARY	25.00	10.00
1	REAR WINDSCREEN SEAL (SN)	NECESSARY	80.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
			265.00	120.00
	<u>LABOUR</u>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		80.00	60.00
	TO REMOVE, REINSTALL WINDSCREEN (REAR).		150.00	120.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR).		100.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	600.00

Report Ref No. CS/AGI23000888/Aqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,000.00	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	60.00
			2,430.00	1,500.00
GRAND TOTAL			6,583.97	4,251.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CS/AGI23000888/Aqy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.