



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTL 3910

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLEBAR (CONSISTENT)	BENT	90.00	90.00
1	CONE BEARING (CONSISTENT)	NECESSARY	80.00	80.00
1	SET COVER (CONSISTENT)	DISTORTED	280.00	280.00
1	HEADLAMP (CONSISTENT)	CUT	80.00	80.00
2	SIGNAL LAMP CONSOLE LEFT /RIGHT @\$40.00 (CONSISTENT)	CUT	80.00	80.00
1	HEADLAMP INNER PANEL (CONSISTENT)	DISTORTED	50.00	50.00
1	SWING ARM (CONSISTENT)	BENT	280.00	200.00
1	PILLION BAR (CONSISTENT)	CUT	40.00	40.00
1	BASKET FRONT (CONSISTENT)	CUT	25.00	25.00
	LESS 10% DISCOUNT		-	-92.50
			1,005.00	832.50
	<u>SPECIAL NETT ITEMS</u>			
1	FORK LEFT/RIGHT (SN) (CONSISTENT) }	BENT	180.00	120.00
1	TO FORK BRACKET (SN) (CONSISTENT) }	NECESSARY	180.00	-
			360.00	120.00
	<u>LABOUR</u>			
	LABOUR .		150.00	150.00
			150.00	150.00
	GRAND TOTAL		1,515.00	1,102.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			900.00

Report Ref No. CC4/ASM23000890/Tpa3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.