

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 7557K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	NOT NECESSARY	1,945.20	-
2	REAR TAILGATE LATCH	NOT NECESSARY	390.00	-
2	REAR TAILGATE SIDE MEMBER WITH RUBBER	TO REPAIR SEE LABOUR	536.00	-
2	REAR TAILGATE HINGES	TO REPAIR SEE LABOUR	136.00	-
1	REAR TAILGATE LOWER MEMBER	TO REPAIR SEE LABOUR	749.40	-
2	REAR TAILLAMPS	O/S CRACKED / N/S NOT NECESSARY	750.00	288.50
2	REAR TAILLAMP BRACKETS	NOT NECESSARY	238.40	-
1	REAR NUMBER PLATE BRACKET	NOT NECESSARY	155.00	-
1	REAR NUMBER LAMP	NOT NECESSARY	175.00	-
1	REAR TIRE CARRIER	NOT NECESSARY	385.00	-
	LESS 25% DISCOUNT		-1,365.00	-72.13
			4,095.00	216.37
	SPECIAL NETT ITEMS			
1	REAR "13PAX" STICKER (SN)	NOT NECESSARY	35.00	-
1	REAR "70KM/H" STICKER (SN)	NOT NECESSARY	35.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
1	REAR NUMBER PLATE (SN)	BENT	35.00	20.00
			385.00	20.00
	<u>LABOUR</u>			
	TO REMOVE,REPLACE & CHECK UP WIRING.		50.00	20.00
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	200.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAILGATE SIDE MEMBER WITH RUBBER,REAR TAILGATE HINGES AND REAR TAILGATE LOWER MEMBER.		1,200.00	300.00
	TO RE-SPRAY THE AFFECTED AREAS.		1,000.00	200.00
			2,450.00	520.00
	GRAND TOTAL		6,930.00	756.37

Report Ref No. CS/SMO23000894/Uqy3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO23000894/Uqy3e2

CHUA KANG SENG

Licensed Appraiser