

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000895/UPA3Q2**Date:** 19/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210027450
Claimant Vehicle No :	SLD9552B	Insured Vehicle No :	SMY7080L
Date of Loss:	22/01/2023	Nature of Claim:	TP
		Claim No:	1944274303SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD9552B	Engine No:	L13B1320518
Make & Model:	HONDA FIT, 1.3 G F-Package (A)	Chassis No:	GK31217914
Reg. Date:	01/07/2016 (Man. Year: 2016)	Odometer:	83074 km
Colour:	Blue		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,530.08	3,341.20	2,188.88	39.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,660.00	470.00	22.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,660.08	5,001.20	2,658.88	34.71
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	7,660.08	3,500.00	4,160.08	54.31
+ GST 8.00/8.00% (S\$)	612.81	280.00	332.81	54.31
Nett Amount (S\$)	8,272.89	3,780.00	4,492.89	54.31
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Medical Costs (S\$)		470.80		
Nett Liability (S\$)		4,610.80		

INSPECTION

Date of Assignment:	30/01/2023	Hock Wah Motor Workshop Pte Ltd (Bedok)
Date Inspected:	30/01/2023 Inspected At:	Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012
Estimated Period of Repair:	4.0 days	Singapore 489977

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	575.90 FL	*575.90 FL
2	1		*BONNET HINGE RH	Not Necessary	40.00 FL	*- FL
3	1		*BONNET HINGE LH	Not Necessary	40.00 FL	*- FL
4	1		*SUPPORT PANEL	Bent	420.80 FL	*420.80 FL
5	1		*SUPPORT PANEL TOP GARNISH	Not Necessary	28.00 FL	*- FL
6	1		*SUPPORT PANEL INNER CENTER GARNISH LH (NPA)	Not Necessary	0.00 FL	*- FL
7	1		*RADIATOR	Not Necessary	1,250.00 FL	*- FL
8	1		*RADIATOR COWLING	Not Necessary	125.00 FL	*- FL
9	1		*RADIATOR FAN	Not Necessary	65.00 FL	*- FL
10	1		*RADIATOR MOTOR	Not Necessary	362.90 FL	*- FL
11	1		*AIR CON CONDENSER	Punctured	810.00 FL	*810.00 FL
12	1		*FRONT GRILLE ASSEMBLY	Cracked	356.00 FL	*356.00 FL
13	1		*FRONT BUMPER	Deformed	901.70 FL	*635.00 FL
14	1		*FRONT BUMPER RETAINER LH	Bent	15.00 FL	*15.00 FL
15	1		*FRONT BUMPER RETAINER RH	Bent	15.00 FL	*15.00 FL
16	1		*FRONT BUMPER BRACKET RH	Not Necessary	30.90 FL	*- FL
17	1		*FRONT BUMPER BRACKET LH	Not Necessary	30.90 FL	*- FL
18	1		*FRONT BUMPER REINFORCEMENT	Repair	246.70 FL	*- FL
19	1		*FRONT BUMPER LOWER GARNISH	Torn	30.90 FL	*30.90 FL
20	1		*FRONT BUMPER SIDE GRILLE RH	Missing	30.90 FL	*30.90 FL
21	1		*HEADLAMP LH	Cracked	583.50 FL	*583.50 FL
22	1		*HEADLAMP RH	Cracked	583.50 FL	*583.50 FL
23	1		*HEADLAMP BRACKET RH	Cracked	35.00 FL	*35.00 FL
24	1		*HEADLAMP BRACKET LH	Cracked	35.00 FL	*35.00 FL
25	1		*FRONT FENDER LH (NPA)	Repair	0.00 FS	*- FS
26	1		*FRONT FENDER RH (NPA)	Repair	0.00 FS	*- FS
27	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*20.00 FS
28	1		*FRONT NUMBER PLATE HOLDER	Bent	30.00 FS	*20.00 FS
29	1		*RADIATOR COOLANT	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,852.60	4,166.50
- List Item Discount on L Items 20.00/20.00% (\$)	1,322.52	825.30
Total Parts (\$)	5,530.08	3,341.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	700.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	800.00
3	ANTI-RUST COATING	New	150.00	60.00
4	TO SERVICE & TOP-UP AIR-CON GAS	New	180.00	100.00
Gross Labour Cost (\$\$)			2,130.00	1,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >