



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 760P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	UNBEKANNT REAR BOOT LID (SN)	BENT	4,850.19	4,850.19
2	1K WINDOW ADHESIVE @\$50.73 (SN)	NECESSARY	101.46	101.46
1	ALL PURPOSE CLEANER (SN)	NECESSARY	84.67	84.67
1	PRIMER (SN)	NECESSARY	24.91	24.91
1	ACTIVATOR (SN)	NECESSARY	21.62	21.62
2	APPLICATOR @\$9.19 (SN)	NECESSARY	18.38	18.38
2	RIVETTED CAP NUT @\$2.81 (SN)	NECESSARY	5.62	5.62
1	UNBEKANNT EMBLEM - SKODA (SN)	NECESSARY	99.13	99.13
1	INSCRIPTIO NAME PLATE - SKODA (SN)	NECESSARY	75.51	75.51
1	LETTERING NAME PLATE - KODIAQ (SN)	NECESSARY	110.32	110.32
1	HOOD LATCH BOOT LID LOCK (SN)	NOT NECESSARY	236.07	-
1	BUMP STRIP BUMPER UPPER GRILLE (SN)	NOT NECESSARY	262.50	-
1	COVER FOR REAR BUMPER (UPPER) (SN)	TO REPAIR SEE LABOUR	2,208.62	-
1	COVER FOR REAR BUMPER (LOWER) (SN)	CUT	473.82	473.82
1	SENSOR BRACKET (SN)	NECESSARY	19.51	19.51
1	SENSOR BRACKET (SN)	NECESSARY	19.51	19.51
1	SENSOR BRACKET (SN)	NECESSARY	15.25	15.25
1	SENSOR BRACKET (SN)	NECESSARY	15.25	15.25
1	SENSOR BRACKET (SN)	NECESSARY	15.25	15.25
1	SENSOR BRACKET (SN)	NECESSARY	15.25	15.25
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	84.64	84.64
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	74.37	74.37
2	DOUBLE COLLARED STUD @\$9.93 (SN)	NOT NECESSARY	19.86	-
2	SHOULDERED NUT @\$3.38 (SN)	NECESSARY	6.76	6.76
1	FORM REINF REINFORCEMENT (SN)	NOT NECESSARY	149.31	-
1	RETAINING BUMPER CTR BRACKET (SN)	NOT NECESSARY	92.64	-
1	GUIDE PLEC LHR BUMPER BRACKET (UPPER) (SN)	NOT NECESSARY	57.96	-
1	GUIDE PLEC RHR BUMPER BRACKET (UPPER) (SN)	NOT NECESSARY	57.96	-
1	GUIDE PLEC LHR BUMPER BRACKET (SIDE) (SN)	NOT NECESSARY	57.96	-
1	GUIDE PIEC RHR BUMPER BRACKET (SIDE) (SN)	NOT NECESSARY	57.96	-

Report Ref No. CS/GAI23000897/Rvy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	SCRATCHED	80.00	80.00
1	HIGH-MOUNT 3RD BRAKELIGHT (SN) (ADDITIONAL)	NECESSARY	186.64	186.64
			9,598.90	6,398.06
	LABOUR			
	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR.		280.00	280.00
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	LABOUR. INCLUSIVE OF THE REPAIR OF COVER FOR REAR BUMPER (UPPER).		4,200.00	1,680.00
	SPRAY PAINT.		3,200.00	1,600.00
	R&R REAR W/SCREEN.		840.00	840.00
	TRANSFER BOOT LID MECHANISM.		840.00	420.00
	REAR WATER LEAK TEST.		150.00	150.00
			9,990.00	5,450.00
	GRAND TOTAL		19,588.90	11,848.06
RECOMMENDED COST OF REPAIRS				11,848.06

Report Ref No. CS/GAI23000897/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.