

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711**Our File No:** CS/III23000900/KWY3M4**Date:** 03/04/2023**REFERENCE**

Insured/Claimant:	ONG SWEE HENG	Policy No:	D22MPC0008471	
Date of Loss:	14/01/2023	Nature of Claim:	OD	Claim No: MPC2023D0000629

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJL3113G</b>		
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (R18) (A)	Engine No:	27492030195206
Reg. Date:	02/07/2014 (Man. Year: 2014)	Chassis No:	WDD2120362B029822
Colour:	Metallic Silver	Odometer:	198834 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	S\$60,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/40 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	16,285.50	5,753.00	10,532.50	64.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,360.00	1,340.00	49.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>18,985.50</b>	<b>7,113.00</b>	<b>11,872.50</b>	<b>62.53</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,700.00</b>		
<b>- Excess (\$\$)</b>	750.00	750.00	0.00	0.00
<b>(\$\$)</b>	18,235.50	4,950.00	13,285.50	72.86
<b>+ GST 8.00/8.00% (\$\$)</b>	1,458.84	396.00	1,062.84	72.86
<b>Nett Amount (\$\$)</b>	<b>19,694.34</b>	<b>5,346.00</b>	<b>14,348.34</b>	<b>72.86</b>

**INSPECTION**

Date of Assignment: 30/01/2023

Date Inspected: 01/02/2023 Inspected At:

BODYFIX  
NO 10 ANG MO KIO INDUSTRIAL PARK 2A  
#04-06 AMK AUTOPOINT  
SINGAPORE 568047

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2023)
Parts:	143	MERCEDES-BENZ E250 2.0 SEDAN (R18) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJL3113G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Bent	1,350.00 F	*855.00 F
2	1		*FRONT BUMPER REINFORCEMENT (WCP)	Buckled	550.00 F	*310.00 F
3	1		*FRONT BUMPER SPONGE (WCP)	Cracked	220.00 F	*75.00 F
4	2		*FRONT BUMPER SENSOR (WCP)	Serviceable	360.00 F	*- F
5	1		*FRONT GRILLE BASE (WCP)	Cracked	300.00 F	*300.00 F
6	1		*FRONT GRILLE CHROME (WCP)	Cracked	350.00 F	*350.00 F
7	1		*FRONT GRILLE LOGO (WCP)	Cracked	120.00 F	*55.00 F
8	1		*FRONT GRILLE LOGO GARNISH (WCP)	Cracked	200.00 F	*200.00 F
9	1		*FRONT GRILLE OUTER GARNISH (WCP)	Cracked	250.00 F	*250.00 F
10	1		*BONNET (WCP)	Bent	1,800.00 F	*1,450.00 F
11	1		*BONNET LOCK (WCP)	Distorted	100.00 F	*100.00 F
12	1		*BONNET INSULATOR (WCP)	Serviceable	250.00 F	*- F
13	1		*BONNET LOGO (WCP)	Missing	65.00 F	*65.00 F
14	1		*BONNET CATCH (WCP)	Repair	150.00 F	*- F
15	1		*FRONT SUPPORT PANEL (WCP)	Repair	650.00 F	*- F
16	1		*FRONT SUPPORT PANEL TOP GARNISH (WCP)	Cracked	250.00 F	*120.00 F
17	1		*HEAD LAMP (LH) (WCP)	Serviceable	3,350.00 F	*- F
18	1		*HEAD LAMP (RH) (WCP)	Serviceable	3,350.00 F	*- F
19	1		*FRONT NO.PLATE (WCP)	Serviceable	40.00 F	*- F
20	1		*RADIATOR (WCP)	Punctured	450.00 F	*450.00 F
21	1		*CONDENSER (WCP)	Bent	400.00 F	*400.00 F
22	1		*FRONT SUPPORT PANEL TOP (WCP)	Bent	250.00 F	*250.00 F

F=Franchise part.

Sub Total (\$\$)	14,805.00	5,230.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	1,480.50	523.00
Total Parts (\$\$)	16,285.50	5,753.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR & RE-ALIGN DAMAGE PARTS	New	1,200.00	700.00
2	TO SPRAY PAINT FRONT BUMPER, BONNET & OTHER AFFECTED AREAS	New	1,500.00	660.00
<b>Gross Labour Cost (S\$)</b>			<b>2,700.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >