

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG23000910/UYA3Q2**Date:** 20/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700054187
Claimant Vehicle No :	FBP1194J	Insured Vehicle No :	SBX5006B
Date of Loss:	25/01/2023	Nature of Claim:	TP
		Claim No:	5780314271SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP1194J	Engine No:	KC32E0031582
Make & Model:	HONDA CB150R, 149cc	Chassis No:	MLHKC2884J5031582
Reg. Date:	11/02/2019 (Man. Year: 2018)	Odometer:	40433 km
Colour:	Green		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	100/80 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,507.00	3,042.10	1,464.90	32.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	300.00	250.00	45.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,057.00	3,342.10	1,714.90	33.91
Approved Total (Overridden) (\$\$)		2,650.00		
Nett Amount (\$\$)	5,057.00	2,650.00	2,407.00	47.60
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	31/01/2023	Ban Hock Hin Co. Pte Ltd (HQ)4
Date Inspected:	31/01/2023 Inspected At:	BLK 8 Defu South Street 1, #04-28 JTC Defu Industrial City
Estimated Period of Repair:	4.0 days	Singapore 533758

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE REAR WHEEL	*Check	85.00 F	*- F
2	1		*BALANCER HANDLE	Cut	18.00 F	*18.00 F
3	1		*BAR HANDLE	*Check	95.00 F	*- F
4	1		*BOLT HEX CAP	*Check	8.00 F	*- F
5	1		*BOLT-WASHER SIGNAL 5X25	*Check	13.00 F	*- F
6	1		*BOX REAR (KAPPA)K35N W/O LIGHT BLACK	Cut	280.00 F	*280.00 F
7	1		*BRACKET (HD) BOX REAR	Bent	203.00 F	*203.00 F
8	1		*BRACKET FOOTREST	Bent	34.00 F	*34.00 F
9	1		*BRACKET FOOTREST REAR RH	Cut	56.00 F	*56.00 F
10	1		*COLLAR LAMP SIGNAL	*Check	18.00 F	*- F
11	1		*COLLAR SPROCKET REAR	*Check	35.00 F	*- F
12	1		*COLLAR STEP LOWER	*Check	8.00 F	*- F
13	1		*COVER FENDER LOWER REAR	Distorted	24.00 F	*24.00 F
14	1		*COVER LICENSE LIGHT (WL)	Distorted	24.00 F	*24.00 F
15	1		*COVER SIDE UPPER RH	Distorted	36.00 F	*36.00 F
16	1		*COVER UNDER RH	Distorted	36.00 F	*36.00 F
17	1		*FENDER REAR A	Distorted	36.00 F	*36.00 F
18	1		*FOOTREST REAR RH	Cut	36.00 F	*36.00 F
19	1		*FOOTREST RH	Cut	86.00 F	*86.00 F
20	1		*GRILE HANDLE RH	Torn	32.00 F	*32.00 F
21	1		*GUARD CHAIN	Torn	39.00 F	*39.00 F
22	1		*HOLDER RH STEP	Cut	49.00 F	*49.00 F
23	1		*LAMP SIGNAL REAR LH	Cracked	75.00 F	*75.00 F
24	1		*LAMP SIGNAL REAR RH	Cracked	90.00 F	*90.00 F
25	1		*LEVER BRAKE (SILVER)	Bent	28.00 F	*28.00 F
26	1		*LICENSE LIGHT ASSY	Cracked	109.00 F	*109.00 F
27	1		*MASTER CYLINDER PUMP REAR	Twisted	109.00 F	*109.00 F
28	1		*METER IU (12V) NEW MODEL	Serviceable	310.00 F	*- F
29	1		*MIRROR LH ASSY	Not Necessary	62.00 F	*- F
30	1		*MIRROR RH ASSY	Cut	62.00 F	*62.00 F
31	1		*PEDAL BRAKE	Bent	36.00 F	*36.00 F
32	1		*PIN SPLIT 1.6 FOOTREST	Necessary	8.00 F	*8.00 F
33	1		*PIN STEP BAR JOINT	Necessary	8.00 F	*8.00 F
34	1		*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	24.00 F	*24.00 F
35	1		*RIM SPORT FRONT	Cut	565.00 F	*565.00 F
36	1		*RIM SPORT REAR ASSY	Bent	613.00 F	*613.00 F
37	4		*RUBBER HANDLE	*Check	52.00 F	*- F
38	1		*RUBBER MOUNTING LAMP SIGNAL RH	Twisted	21.00 F	*21.00 F
39	1		*SCREW TAPPING 4X16 LICENSE LIGHT	*Check	26.00 F	*- F
40	1		*SPRING FOOTREST RH	Necessary	13.00 F	*13.00 F
41	1		*STAY FENDER REAR LH	Bent	78.00 F	*78.00 F
42	1		*STAY FENDER REAR RH	Bent	78.00 F	*78.00 F
43	1		*SWINGARM SUB ASSY	*Check	698.00 F	*- F
44	1		*TYRE 150/60-17 (PIRELLI) ROSSO 3 (70%)	Punctured	183.00 F	*128.10 F
45	1		*WASHER FOOTREST 15.5X27X2.0	Necessary	8.00 F	*8.00 F

F=Franchise part.

Total Parts (S\$) **4,507.00** **3,042.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLE & INSTALLATION OF PARTS	New	550.00	300.00
Gross Labour Cost (\$\$)			550.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >