

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS23000912/UYA3Q2**Date:** 20/07/2023**REFERENCE**

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2001527876
Claimant Vehicle No :	SLL9898L	Insured Vehicle No :	SJK9225H
Date of Loss:	27/01/2023	Nature of Claim:	TP
		Claim No:	202332004881

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL9898L		
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Engine No:	2NRX785211
Reg. Date:	21/01/2022 (Man. Year: 2021)	Chassis No:	MHFZ28H3900072852
Colour:	Grey	Odometer:	36566 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,753.60	4,320.40	2,433.20	36.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,569.41	4,635.41	4,934.00	51.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,323.01	8,955.81	7,367.20	45.13
+ GST 8.00/8.00% (S\$)	1,305.84	716.46	589.38	45.13
Nett Amount (S\$)	17,628.85	9,672.27	7,956.58	45.13
+ Car Rental (7.0 x S\$75.00/day + 8.00% GST) (S\$)		567.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,241.27		

INSPECTION

Date of Assignment:	30/01/2023		
Date Inspected:	06/02/2023	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jul 2023)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL9898L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
2	1		*SEALANT FOR REAR LH DOOR	Necessary	60.00 FS	*60.00 FS
3	1		*PANEL SUB-ASSY ,RR D	Dented / Bent	1,556.50 FS	*1,556.50 FS
4	1		*MOULDING SUB-ASSY ,R	Cut	134.50 FS	*134.50 FS
5	1		*MOULDING SUB-ASSY ,Q	Cut	51.60 FS	*51.60 FS
6	1		*PANEL SUB-ASSY ,QUAR	Repair	801.80 FS	*- FS
7	1		*PANEL BONNET AD	Not Necessary	267.20 FS	*- FS
8	1		*WINDOW ASSY	Not Necessary	381.20 FS	*- FS
9	1		*SIKA 1820 SIKA TACK GO (BLA)	Not Necessary	108.00 FS	*- FS
10	1		*SIKA 207 G+P ADHESIVE PRIMER	Not Necessary	200.00 FS	*- FS
11	1		*COVER,RR BUMPER L/	Repair	379.80 FS	*- FS
12	1		*EXTENSION ,RR BUMPER	Grazed	154.60 FS	*154.60 FS
13	10		*PIECE ,RR BUMPER	Not Necessary	49.00 FS	*- FS
14	1		*SUPPORT ,RR BUMPER S	Not Necessary	88.10 FS	*- FS
15	1		*RETAINER ,RR BUMPER	Not Necessary	84.60 FS	*- FS
16	1		*SEAL ,RR BUMPER SIDE	Not Necessary	73.50 FS	*- FS
17	1		*WHEEL ,DISC	Cut	2,333.20 FS	*2,333.20 FS
Total Parts (\$\$)					6,753.60	4,320.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY AND INSTALL REAR LH QUARTER GLASS 3M SOLAR FILM	New	190.00	0.00
2	TO RESET ECU AND REPROGRAMME	New	198.00	198.00
3	TO CHECK WIRING AND LIGHTING TO WATER TEST FOR LEAK	New	134.64	134.64
4	R/I REAR LH QUARTER GLASS TO FACILIATE REPAIRS	New	396.00	0.00
5	TO TRANSFER REAR LH DOOR GLASS ,BOARD ,MOTOR ,REGULATOR AND OTHER ATTACHMENT TO NEW PANEL	New	396.00	396.00
6	TO CONDUCT WHEEL ALIGNMENT CHECK	New	198.00	0.00
7	TO TRANSFER REAR LH TYRE TO NEW SPORT -RIM AND BALANCE	New	80.00	80.00
8	TO REPAIR /REPLACE REAR LH SIDE ACCIDENT DAMAGE PARTS .STRAIGHTEN /REALIGN ALL OTHER AFFECTED AREAS	New	4,752.00	1,584.00
9	TO SPRAY PAINT ON REAR LH SIDE ACCIDENT AFFECTED AREAS	New	2,950.00	1,968.00
10	LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	New	274.77	274.77
Gross Labour Cost (S\$)			9,569.41	4,635.41

Report was unsubmitted during this print-out.

< END OF ESTIMATES >