

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 1719M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	CRACKED	639.80	639.80
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	401.20	-
1	FRONT BUMPER CENTRE LOWER GRILLE (CONSISTENT)	DENTED	204.20	204.20
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	DISTORTED	94.20	94.20
6	FRONT BUMPER CLIPS @\$3.50 (CONSISTENT)	NECESSARY	21.00	21.00
1	FRONT GRILLE (CONSISTENT)	CRACKED	770.80	770.80
1	FRONT GRILLE TOP GARNISH (CONSISTENT)	CUT	86.90	86.90
4	FRONT GRILLE TOP GARNISH CLIPS @\$3.50 (CONSISTENT)	NECESSARY	14.00	14.00
2	HEADLAMPS @\$3604.80 (CONSISTENT)	N/S MTG BROKEN / O/S SERVICEABLE	7,209.60	3,604.80
1	HEADLAMP TOP MOUNTING LH (CONSISTENT)	SERVICEABLE	173.30	-
1	FRT SUPPORT PANEL (CONSISTENT)	BUCKLED	1,226.80	1,226.80
1	FRT BRACE PANEL (CONSISTENT)	DISTORTED	175.80	175.80
1	BONNET (CONSISTENT)	BENT	1,498.60	1,498.60
1	AIR-CON CONDENSER (CONSISTENT)	PUNCTURE	1,404.00	1,404.00
1	FRONT LH FENDER EMBLEM -WTI (CONSISTENT)	NOT NECESSARY	70.70	-
	LESS 25% DISCOUNT		-3,497.73	-2,435.23
			10,493.17	7,305.67
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE (SN) (CONSISTENT)	MISSING	35.00	35.00
			35.00	35.00
	<u>LABOUR</u>			
	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM ,REFILL GAS .		100.00	100.00
	TO PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		700.00	600.00
	TO PUTTY AND RESPRAY ON FRT AFFECTED AREAS .		700.00	650.00
			1,500.00	1,350.00
	GRAND TOTAL		12,028.17	8,690.67

Report Ref No. CC4/ASM23000915/Kpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		6,950.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM23000915/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser