



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303473

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 01/06/2023
Reference CC6/CTI23000927/Kya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMY 5055Z
Insured Veh. SMC 3225D
Claim No. SNM23D200644/C02
Policy No. DMPCSNW00143002202
Accident Date 21/01/2023
Inspection Date 26/01/2023

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI23000927/Kya3q2 Date: 01/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMC 3225D	Veh. Inspected	SMY 5055Z	
Policy No.	DMPCSNW00143002202	Coverage (\$)	0.00	
Claim No.	SNM23D200644/C02	Excess (\$)	0.00	
Assign From		Assign Date	26/01/2023	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	KMHLN41ETNU154592	Colour	METALLIC BLACK	
Odometer	39934 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HANKOOK	7 mm	
L/H Front Tyre	205/55 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/01/2023	Inspection Date	26/01/2023	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMY 5055Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT	580.00	495.00
1	REAR BUMPER LOWER	BENT	420.00	341.00
10	REAR BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
1	REAR BUMPER LOWER REFLECTOR RH	SERVICEABLE	60.00	-
1	REAR BUMPER LOWER REFLECTOR LH	CRACKED	60.00	60.00
1	REAR REINFORCEMENT	CRACKED	320.00	294.00
1	REAR BUMPER RETAINER RH	SERVICEABLE	40.00	-
1	REAR BUMPER RETAINER LH	DISTORTED	40.00	40.00
1	REAR BUMPER UNDER COVER LH	SERVICEABLE	40.00	-
1	REAR INSERT AIR GRILLE VENT LH	SERVICEABLE	40.00	-
1	REAR FENDER REAR SHIELD LH	SERVICEABLE	80.00	-
1	REAR AVANTE EMBLEM	NECESSARY	40.00	40.00
1	REAR BOOTLID	BENT	2,100.00	1,782.00
1	REAR BOOTLID INNER TRIM	BUCKLED	150.00	150.00
1	REAR BOOTLID HINGE RH	TO REPAIR SEE LABOUR	150.00	-
1	REAR BOOTLID HINGE LH	TO REPAIR SEE LABOUR	150.00	-
1	REAR BOOTLID LOWER LATCH	TO REPAIR SEE LABOUR	30.00	-
1	REAR BOOTLID LOCK	DENTED	120.00	120.00
1	REAR BOOTLID RUBBER SEAL	DISTORTED / DENTED	120.00	120.00
1	END PANEL	BENT	600.00	456.00
1	END PANEL GARNISH	BUCKLED	80.00	80.00
1	REAR MAT LUGGAGE COVER	SERVICEABLE	220.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	280.00	-
1	TAIL LAMP RH	SERVICEABLE	680.00	-
1	TAIL LAMP LH	DENTED / CUT	680.00	680.00
2	TAIL LAMP SPECIAL CLIP @\$5.00	NOT NECESSARY	10.00	-
1	BOOTLID LAMP CENTER	SERVICEABLE	1,100.00	-
2	REAR LICENSE LAMP @\$40.00	DENTED	80.00	80.00

Report Ref No. CC6/CTI23000927/Kya3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REVERSE SENSOR @\$180.00	SHORTED (2 PCS ONLY)	720.00	360.00
1	REVERSE SENSOR HARNESS CABLE	SERVICEABLE	250.00	-
1	REAR CORNER RADAR LH	CRACKED	1,200.00	1,120.00
	LESS 20% DISCOUNT		-	-1,249.60
			10,470.00	4,998.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE WITH FRAME (SN)	BENT	40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	SPRAY PAINTING WHOLE REAR .		800.00	600.00
	REPLACE REAR INCLUDING FITTING ,CUT ,WELD AND RE-ALIGN .		1,000.00	600.00
	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR .		80.00	60.00
	RESET AND PROGRAM BLINDSPOT RADAR SENSOR .		280.00	120.00
	APPLY RUST PROOFING ON REPLACED /REPIARED PANEL.		100.00	60.00
	CHECK AND RECTIFY ELECTRICAL WIRING .		30.00	20.00
			2,290.00	1,460.00
GRAND TOTAL			12,800.00	6,498.40
RECOMMENDED COST OF REPAIRS				6,498.40

Report Ref No. CC6/CTI23000927/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMY 5055Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMY 5055Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMY 5055Z

RE-INSPECTION

