

ASS. REC. BY:

REF:

C12 / 23000927/KCP

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1.34%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Pmy 50557

Yr Regn:

03, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Avante

C.C.

1398

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

39934

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHLN41ETNU 154592

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

/ Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

21/1/23

D.O.I.

26/1/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/12

86498.40

Cuh

18/12/23

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) S + RS. SI

) Fines

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2301-042

DATE : 25-Jan-2023

POLICY NO. : AUTO&GEN P10708655R00

VEHICLE REG. NO. : SMY5055Z

VEHICLE MAKE : HYUNDAI CN7 AVANTE 1.6 DOHC CVT S

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

NOT AUTHORIZED
Penalty B4 point

86498.40

5 days

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>493</i>	<i>RH</i> 1	\$ 580.00	\$ 580.00
2	Rear Bumper Lower <i>341</i>	<i>RH</i> 1	\$ 420.00	\$ 420.00
3	Rear Bumper Clips	<i>10</i>	\$ 3.00	\$ 30.00
4	Rear Bumper Lower Reflector RH	<i>1</i>	\$ 60.00	\$ 60.00
5	Rear Bumper Lower Reflector LH	<i>1</i>	\$ 60.00	\$ 60.00
6	Rear Reinforcement <i>294</i>	<i>1</i>	\$ 320.00	\$ 320.00
7	Rear Bumper Retainer RH	<i>1</i>	\$ 40.00	\$ 40.00
8	Rear Bumper Retainer LH	<i>1</i>	\$ 40.00	\$ 40.00
9	Rear Bumper Under Cover LH	<i>1</i>	\$ 40.00	\$ 40.00
10	Rear Insert Air Grille Vent LH	<i>1</i>	\$ 40.00	\$ 40.00
11	Rear Fender Rear Shield LH	<i>1</i>	\$ 80.00	\$ 80.00
12	Rear Avante Emblem	<i>1</i>	\$ 40.00	\$ 40.00
13	Rear Bootlid <i>1782</i>	<i>1</i>	\$ 2,100.00	\$ 2,100.00
14	Rear Bootlid Inner Trim	<i>1</i>	\$ 150.00	\$ 150.00
15	Rear Bootlid Hinge RH	<i>1</i>	\$ 150.00	\$ 150.00
16	Rear Bootlid Hinge LH	<i>1</i>	\$ 150.00	\$ 150.00
17	Rear Bootlid Lower Latch	<i>1</i>	\$ 30.00	\$ 30.00
18	Rear Bootlid Lock	<i>1</i>	\$ 120.00	\$ 120.00
19	Rear Bootlid Rubber Seal	<i>1</i>	\$ 120.00	\$ 120.00
20	End Panel <i>456</i>	<i>1</i>	\$ 600.00	\$ 600.00
21	End Panel Garnish	<i>1</i>	\$ 80.00	\$ 80.00
22	Rear Mat Luggage Cover	<i>1</i>	\$ 220.00	\$ 220.00
23	Rear Floor Panel	<i>1</i>	\$ 280.00	\$ 280.00
24	Tail lamp RH	<i>1</i>	\$ 680.00	\$ 680.00
25	Tail lamp LH	<i>1</i>	\$ 680.00	\$ 680.00
26	Tail lamp Special Clip	<i>2</i>	\$ 5.00	\$ 10.00
27	Bootlip lamp Center	<i>1</i>	\$ 1,100.00	\$ 1,100.00
28	Rear License Lamp	<i>2</i>	\$ 40.00	\$ 80.00
29	Reverse Sensor	<i>2</i>	\$ 180.00	\$ 720.00
30	Reverse Sensor Harness Cable	<i>1</i>	\$ 250.00	\$ 250.00
31	Rear Corner Radar LH <i>1180</i>	<i>1</i>	\$ 1,200.00	\$ 1,200.00
Total Spare Parts				\$ 10,470.00



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2301-042
DATE : 25-Jan-2023
POLICY NO. : AUTO&GEN P10708655R00
VEHICLE REG. NO. : SMY5055Z
VEHICLE MAKE : HYUNDAI CN7 AVANTE 1.6 DOHC CVT S

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPECIAL NETT			
32	Rear Number Plate with Frame <i>R1</i>	1	\$ 40.00	\$ 40.00
	Total Special Nett			\$ 40.00
	LABOUR			
33	Spray Painting Whole Rear	1	\$ 800.00	\$ 800.00
34	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,000.00	\$ 1,000.00
35	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
36	Reset and Program Blindspot Radar Sensor	1	\$ 280.00	\$ 280.00
37	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
38	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

✓
600/
600/
601
720/
60k
201

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.

Total Labour	\$ 2,290.00
Amount Before Excess	\$ 12,800.00
Add GST @ 7%	896.00
Total Amount Payable	\$ 13,696.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: