

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01 (Claims & Performance Management)  
Singapore 068897**Our File No:** CS/AIS23000930/KVP3Q2**Date:** 27/07/2023**REFERENCE**

|                   |                |                  |              |
|-------------------|----------------|------------------|--------------|
| Insured/Claimant: | LIM PENG CHUAN | Policy No:       | SP2001166783 |
| Date of Loss:     | 02/12/2022     | Nature of Claim: | OD           |
|                   |                | Claim No:        | 202222008648 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKP9899A</b>                   | Engine No:  | 2ARF518203        |
| Make & Model:               | LEXUS ES250, 2.5 (A)              | Chassis No: | JTHBJ1GG902106593 |
| Reg. Date:                  | 15/03/2018 (Man. Year: 2017)      | Odometer:   | 79578 km          |
| Colour:                     | Metalic Light Grey                |             |                   |
| Engine Capacity:            | 2494 cc                           |             |                   |
| Market Value/New Car Price: | S\$125,000.00                     |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 215/55 R17       | Rear Tyre Size:  | 215/55 R17       |
| Front Left Side:  | Continental 7 mm | Rear Left Side:  | Continental 7 mm |
| Front Right Side: | Continental 7 mm | Rear Right Side: | Continental 7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>               | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                               | 12,638.00         | 8,387.02          | 4,250.98          | 33.64         |
| Miscellaneous Items                 | 0.00              | 0.00              | 0.00              |               |
| Labour                              | 3,500.00          | 820.00            | 2,680.00          | 76.57         |
| Paintwork Labour                    | 0.00              | 0.00              | 0.00              |               |
| Towing                              | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b> | <b>16,138.00</b>  | <b>9,207.02</b>   | <b>6,930.98</b>   | <b>42.95</b>  |
| <b>- Excess (S\$)</b>               | 700.00            | 700.00            | 0.00              | 0.00          |
| <b>Nett Amount (S\$)</b>            | <b>15,438.00</b>  | <b>8,507.02</b>   | <b>6,930.98</b>   | <b>44.90</b>  |

**INSPECTION**

|                             |            |               |   |
|-----------------------------|------------|---------------|---|
| Date of Assignment:         | 30/01/2023 |               |   |
| Date Inspected:             | 01/02/2023 | Inspected At: | Cartimes Autolution Pte Ltd (HQ)<br>160 Sin Ming Drive #02-04 Autocity,<br>Singapore 575722 |
| Estimated Period of Repair: | 4.0 days   |               |   |

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|   |   |
|---|---|
| <b>Part Source:</b> MRM-SG  | Version: 1.0 (Last Synchronised: 27 Jul 2023)         |
| <b>Parts:</b> 143   | LEXUS ES250 2.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b> Repairer's   | (Price-denominated Standard List)                     |
| <b>Print Code:</b> (Unsubmitted, no print-code for SKP9899A)  |   |
| <b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition      | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|----------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                        | Bent / Cracked | 1,000.00 FL | *1,000.00 FL |
| 2   | 1   |          | *FRONT BUMPER RETAINER RHS           | Distorted      | 70.00 FL    | *70.00 FL    |
| 3   | 1   |          | *FOG LAMP COVER RHS                  | Dented         | 150.00 FL   | *150.00 FL   |
| 4   | 1   |          | *HEADLAMP RHS                        | Cut            | 6,200.00 FL | *6,200.00 FL |
| 5   | 1   |          | *HEADLAMP BRACKET RHS                | Repair         | 80.00 FL    | *- FL        |
| 6   | 1   |          | *FRONT FENDER RHS                    | Repair         | 1,450.00 FL | *- FL        |
| 7   | 1   |          | *FRONT REINFORCEMENT                 | Bent           | 600.00 FL   | *498.80 FL   |
| 8   | 1   |          | *SUPPORT PANEL                       | Repair         | 1,600.00 FL | *- FL        |
| 9   | 1   |          | *WIPER TANK                          | Dented         | 320.00 FL   | *137.60 FL   |
| 10  | 1   |          | *FRONT GRILLE ASSY                   | Cracked        | 1,200.00 FL | *838.50 FL   |
| 11  | 1   |          | *FRONT GRILLE CHROME GARNISH         | Cracked        | 1,150.00 FL | *312.90 FL   |
| 12  | 1   |          | *SET FRONT BUMPER CLIPS              | Necessary      | 100.00 FS   | *100.00 FS   |
| 13  | 1   |          | *SET FRONT FENDER INNER SHIELD CLIPS | Not Necessary  | 100.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                 |
|--|------------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>14,020.00</b> | <b>9,307.80</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 1,382.00         | 920.78          |
| <b>Total Parts (\$)</b>                                  | <b>12,638.00</b> | <b>8,387.02</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars  | Lab.Type | Repairer's                      | Amount          |
|---------------------|--|----------|---------------------------------|-----------------|
| <b>Labour Items</b> |  |          |                                 |                 |
| 1                   | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS    | New      | 1,600.00                        | 400.00          |
| 2                   | TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED      | New      | 1,600.00                        | 400.00          |
| 3                   | TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS | New      | 100.00                          | 20.00           |
| 4                   | TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS   | New      | 100.00                          | 0.00            |
| 5                   | DIGNOSTIC CHECK  | New      | 100.00                          | 0.00            |
|                     |  |          | <b>Gross Labour Cost (\$\$)</b> | <b>3,500.00</b> |
|                     |  |          |                                 | <b>820.00</b>   |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >