


Not Notair
 Return B4paim
 Ex 3700k
 9207-02



VEHICLE NO: SKP98999A
 CHASSIS NO: JTHBJ1GG902106593

MODEL: LEXUS ES250

DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)
PARTS (LIST ITEMS)	
FRONT BUMPER	BH/cr \$ 1,000.00 ✓
FRONT BUMPER RETAINER RHS	\$ 70.00 ✓
FOG LAMP COVER RHS	\$ 150.00 ✓
HEADLAMP RHS	Car \$ 6,200.00 ✓
HEADLAMP BRACKET RHS	R \$ 80.00 ✓
FRONT FENDER RHS	R \$ 1,450.00 ✓
FRONT REINFORCEMENT	\$ 600.00 ✓
SUPPORT PANEL	R \$ 1,600.00 ✓
WIPER TANK	\$ 320.00 ✓
Front grille assy 1200 crm 838.50	
Front grille Chrome garnish 1150 crm 312.90	
SPECIAL NETT ITEMS	
FRONT BUMPER CLIPS 1 SET	R \$ 100.00 ✓
FRONT FENDER INNER SHIELD CLIPS 1 SET	R \$ 100.00 X
Total	\$ 200.00
TOTAL PARTS	\$ 10,523.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ASS. REC. BY:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00
4	To provide anti-rust treatment on affected areas	\$ NZ 100.00
5	Dignostic Check	\$ NZ 100.00
	Labour Total :	\$ 3,500.00
	TOTAL (PARTS & LABOUR):	\$ 14,023.00

4001

4001

201

X

X