



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 3940S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u> REAR BUMPER ASSY LESS 5% DISCOUNT	SCRATCHED	900.00	900.00
			-45.00	-45.00
			855.00	855.00
20	<u>SPECIAL NETT ITEMS</u> BUMPER CLIPS @\$5.00 (SN) <u>LABOUR</u> TO REMOVE & REPLACE THE DAMAGED PARTS AS LISTED ABOVE, INCLUDING REINSTATEMENTS OF NECESSARY ATTACHMENTS & FITTINGS TO FACILITATE REPAIRS; JACK, PANEL BEAT & RESHAPE THE AFFECTED PARTS & COMPONENTS, CORRECT & REALIGN THE NECESSARY PARTS. TO PROVIDE SKILL LABOUR & MATERIAL TO DO SURFACE TREATMENT / EPOXY TREATMENT AND TO RESPRAY WITH 2K PAINT ON REAR BUMPER WITH OVEN SPRAY BOOTH FACILITIES. TO TRANFER TAILGATE LOCK MECHANISM.	NOT NECESSARY	100.00	-
			100.00	-
			500.00	200.00
		NOT NECESSARY	400.00	250.00
			100.00	-
			1,000.00	450.00
GRAND TOTAL			1,955.00	1,305.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,050.00

Report Ref No. CS/INC23000935/Rvp3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.