

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB23000940/PA3Q2**Date:** 09/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_02

Claimant Vehicle No : SKR3625C **Insured Vehicle No :** SNC7702E

Date of Loss: 23/01/2023 Nature of Claim: TP Claim No: MFL2023D0000960

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKR3625C**
 Make & Model: HONDA ODYSSEY, 2.4 EX-S CVT (A) Engine No: K24W71001844
 Reg. Date: 02/02/2015 (Man. Year: 2014) Chassis No: JHMRC1880EC204309
 Colour: White Odometer: 87228 km
 Engine Capacity: 2356 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 7 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,903.44	4,383.67	2,519.77	36.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,600.00	9,910.00	1,690.00	14.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,503.44	14,293.67	4,209.77	22.75
Approved Total (Overridden) (S\$)		14,293.65		
(S\$)	18,503.44	14,293.65	4,209.79	22.75
+ GST 8.00/8.00% (S\$)	1,480.28	1,143.49	336.79	22.75
Nett Amount (S\$)	19,983.72	15,437.14	4,546.58	22.75
+ Car Rental (13.0 x S\$150.00/day + 8.00% GST) (S\$)		2,106.00		
Nett Liability (S\$)		17,543.14		

INSPECTION

Date of Assignment: 26/01/2023

Date Inspected: 26/01/2023 Inspected At: Kah Motor Co Sdn Bhd (HQ)
 6A MANDAI ESTATE, SINGAPORE 729903
 Singapore 729903

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 May 2023)
Parts:	M1-SUV	HONDA ODYSSEY 2.4 EX-S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR3625C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE COMP	Bent	859.65 FS	*859.65 FS
2	2		*HINGE COMPTAILGATE	Repair	57.30 FS	*- FS
3	1		*WEATHERSTRIP TAILGATE	Distorted / Dented	94.27 FS	*94.27 FS
4	1		*LOCKTAILGATE	Repair	150.30 FS	*- FS
5	1		*GARNISH ASSYRR LICENSE	Distorted	185.02 FS	*185.02 FS
6	1		*MOLDING ASSYRR.LICENSE GARN	Cracked	140.92 FS	*140.92 FS
7	1		*EMBLEMH	Necessary	21.15 FS	*21.15 FS
8	2		*CLIP TUBULAR	Necessary	3.60 FS	*3.60 FS
9	1		*LINING ASSYTAILGATE LOWER	Distorted	165.60 FS	*165.60 FS
10	1		*FACERR BUMPER	Bent	444.52 FS	*444.52 FS
11	1		*SPACERR.RR.BUMPER SIDE	Necessary	15.30 FS	*15.30 FS
12	1		*SPACERL.RR.BUMPER SIDE	Necessary	15.30 FS	*15.30 FS
13	1		*CLIP.BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
14	1		*FACER.RR.BUMPER GARNISH	Buckled	63.52 FS	*63.52 FS
15	1		*FACEL.RR.BUMPER GARNISH	Serviceable	63.52 FS	*- FS
16	1		*REFLECTOR ASSYR.RR	Serviceable	36.37 FS	*- FS
17	1		*REFLECTOR ASSYL.RR	Serviceable	36.37 FS	*- FS
18	1		*PANEL COMP.RR	Bent	369.90 FS	*369.90 FS
19	1		*PAN SET ,3RD SEAT	Bent	271.27 FS	*271.27 FS
20	1		*LINING ASSYRR PANEL	Serviceable	83.17 FS	*- FS
21	1		*COMP LIDTOOL	Serviceable	49.27 FS	*- FS
22	1		*TAILLIGHT ASSYR	Serviceable	672.90 FS	*- FS
23	1		*TAILLIGHT ASSYL	Serviceable	672.90 FS	*- FS
24	1		*LIGHT ASSY ,R.LID	Broken	310.05 FS	*310.05 FS
25	1		*LIGHT ASSYL.LID	Broken	310.05 FS	*310.05 FS
26	1		*ANTENNA ASSY SMAR	Serviceable	61.27 FS	*- FS
27	1		*BUZZER ASSYSMART	Cracked	48.60 FS	*48.60 FS
28	1		*NUMBER PLATE WITH CASING -L	Serviceable	45.00 FS	*- FS
29	4		*ACT RR SENSOR	Dented / Shorted	320.00 FS	*320.00 FS
30	1		*SILENCER COMPEXHAUST	Repair	521.40 FS	*- FS
31	2		*MOULDINGRR.WINDSHIELD SIDE	Necessary	28.80 FS	*28.80 FS
32	1		*MOLDINGR.RR.WINDSHIELD CORNER	Necessary	13.57 FS	*13.57 FS
33	1		*MOLDINGL.RR.WINDSHIELD CORNER	Necessary	13.57 FS	*13.57 FS
34	4		*SPACERRR.W/SHIELD	Necessary	12.60 FS	*12.60 FS
35	1		*RUBBER AWINDSHIELD DAM	Necessary	2.92 FS	*2.92 FS
36	1		*DAMPERSTD 5X5 (2 PCS)	Necessary	13.65 FS	*13.65 FS
37	1		*CAPPIVOT	Necessary	3.90 FS	*3.90 FS
38	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
39	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
40	1		*LINING COMP,R.RR.SIDE	Necessary	504.60 FS	*504.60 FS
41	1		*STOPPERTAILGATE	Necessary	2.85 FS	*2.85 FS
42	1		*OILSHEET	Necessary	32.62 FS	*32.62 FS
43	1		*POCKETTAILGATE LINING PULL	Necessary	8.62 FS	*8.62 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)		6,903.44	4,383.67
Report was unsubmitted during this print-out.			

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RR.WINDSCREEN	New	650.00	650.00
2	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	160.00	160.00
3	REMOVE & RENEW REVERSE SENSORS	New	140.00	140.00
4	RESET VEHICLE SMART ENTRY SYSTEM	New	340.00	340.00
5	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	340.00	340.00
6	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	380.00	380.00
7	REMOVE & TRANSFER ITEMS TO NEW TAILGATE .ADJUST &	New	540.00	540.00
8	APPLY BODY UNDERSIDE COATING	New	250.00	100.00
9	BODY JOINT SEALANT TAILGATE	New	100.00	80.00
10	BODY JOINT SEALANT END PANEL	New	100.00	80.00
11	BODY JOINT SEALANT FLOOR PANEL	New	100.00	80.00
12	CUT & RENEW RR FLOOR PANEL STRAIGHTEN FENDERS ALIG	New	4,500.00	3,900.00
13	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	4,000.00	3,120.00
Gross Labour Cost (S\$)			11,600.00	9,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >