

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI23000942/AQP3M4**Date:** 06/07/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00020052201
Claimant Vehicle No :	SMS3486H	Insured Vehicle No :	SMW1337Y
Date of Loss:	24/01/2023	Nature of Claim: TP	Claim No: SNM23D200674/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS3486H		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Elegance 2WD (A)	Engine No:	1ZR0F21532
Reg. Date:	24/02/2020 (Man. Year: 2020)	Chassis No:	MR2BE3BE100008086
Colour:	Black	Odometer:	33471 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,698.10	9,096.32	3,601.78	28.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,050.00	3,160.00	890.00	21.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,748.10	12,256.32	4,491.78	26.82
Approved Total (Overridden) (S\$)		9,800.00		
(S\$)	16,748.10	9,800.00	6,948.10	41.49
+ GST 8.00/8.00% (S\$)	1,339.85	784.00	555.85	41.49
Nett Amount (S\$)	18,087.95	10,584.00	7,503.95	41.49

INSPECTION

Date of Assignment:	31/01/2023	
Date Inspected:	31/01/2023	Inspected At: N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB, SINGAPORE 417921
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 Elegance 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS3486H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Distorted	905.20 FL	*905.20 FL
2	1		*REAR BOOTLID ALTIS EMBLEM	Necessary	48.30 FL	*48.30 FL
3	1		*REAR BOOTLID COROLLA EMBLEM	Necessary	48.30 FL	*48.30 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	66.20 FL	*66.20 FL
5	2		*REAR BOOTLID HINGES L/R	Bent	150.60 FL	*150.60 FL
6	2		*REAR BOOTLID INNER RUBBER STOPPER L/R	Not Necessary	37.80 FL	*- FL
7	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	83.50 FL	*- FL
8	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	16.20 FL	*- FL
9	1		*REAR BOOTLID MECHANISM LOCK	Damaged	423.90 FL	*256.00 FL
10	2		*REAR BOOTLID NUMBER PLATE LAMP L/R	Not Necessary	139.40 FL	*- FL
11	1		*REAR BOOTLID OUTER CHROME MOULDING	Cracked	209.50 FL	*209.50 FL
12	1		*REAR BOOTLID OUTER CHROME MOULDING GARNISH	Not Necessary	274.70 FL	*- FL
13	2		*REAR BOOTLID REFLECTOR L/R	Cracked	1,551.40 FL	*1,334.00 FL
14	1		*REAR BOOTLID WEATHER STRIP	Cut	219.20 FL	*219.20 FL
15	1		*REAR BUMPER	Distorted	563.00 FL	*563.00 FL
16	2		*REAR BUMPER REFLECTOR L/R	Cracked	82.80 FL	*82.80 FL
17	1		*REAR BUMPER REINFORCEMENT	Dented	353.10 FL	*353.10 FL
18	2		*REAR BUMPER REVERSE SENSOR	Damaged	597.80 FL	*597.80 FL
19	2		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	79.20 FL	*79.20 FL
20	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	213.40 FL	*- FL
21	1		*REAR BUMPER TOW HOOK COVER	Deformed	27.20 FL	*27.20 FL
22	1		*REAR END PANEL	Distorted	653.20 FL	*653.20 FL
23	1		*REAR END PANEL ANTENNA SENSOR	Cracked	76.30 FL	*76.30 FL
24	1		*REAR END PANEL INNER TOP GARNISH	Deformed	286.60 FL	*286.60 FL
25	1		*REAR EXHAUST HEAT COVER	Not Necessary	192.10 FL	*- FL
26	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	104.40 FL	*- FL
27	1		*REAR EXHAUST SILENCER BOX	Not Necessary	1,268.40 FL	*- FL
28	1		*REAR FENDER INNER TRIM BOARD L/R	O/S Torn	786.40 FL	*393.20 FL
29	1		*REAR FLOOR PANEL TOP BOARD COVER	Deformed	987.70 FL	*357.00 FL
30	1		*REAR FLOOR PANEL UNDER COVER	Deformed	471.60 FL	*395.00 FL
31	1		*REAR RH FENDER	Buckled	1,093.60 FL	*1,093.60 FL
32	2		*REAR TAILLAMP INNER PANEL L/R	Buckled	172.00 FL	*172.00 FL
33	2		*REAR TAILLAMP L/R	Cracked	2,595.40 FL	*2,595.40 FL
34	2		*REAR TAILLAMP LOWER BRACKET L/R	Cracked	138.40 FL	*138.40 FL
35	2		*REAR TAILLAMP SIDE COVER L/R	Cut	74.00 FL	*74.00 FL
36	1		*REAR BOOTLID CAMERA	Damaged	900.00 FS	*480.00 FS
37	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*REAR BOOTLID NUMBER PLATE	Dented	25.00 FS	*25.00 FS
39	1		*REAR BOOTLID NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
40	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
41	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
42	2		*SET REAR FENDER INNER TRIM BAORD CLIPS L/R	Necessary	100.00 FS	*30.00 FS
43	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*20.00 FS
44	1		*REAR WINDSCREEN SEAL	Necessary	80.00 FS	*40.00 FS
45	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	16,445.80	11,890.10
				- List Item Discount on L Items 25.00/25.00% (S\$)	3,747.70	2,793.78
				Total Parts (S\$)	12,698.10	9,096.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	500.00	0.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE,REINSTALL WINDSCREEN (REAR)	New	150.00	120.00
4	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	120.00	80.00
5	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER	New	1,400.00	1,200.00
6	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,600.00	1,500.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	100.00
8	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	80.00
Gross Labour Cost (S\$)			4,050.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >