

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CT123000948/TNP3E2**Date:** 28/04/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00021792200
Claimant Vehicle No :	EM2121T	Insured Vehicle No :	SNH6263K
Date of Loss:	20/01/2023	Nature of Claim:	TP
		Claim No:	SNM23D200559/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EM2121T	Engine No:	AM1134725
Make & Model:	ASTON MARTIN VANQUISH, 5.9 (M)	Chassis No:	SCFLCCFP6DGJ00256
Reg. Date:	07/02/2013 (Man. Year: 2012)	Odometer:	53094 km
Colour:	White		
Engine Capacity:	5935 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R20	Rear Tyre Size:	255/35 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	56,826.95	4,950.00	51,876.95	91.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,500.00	1,850.00	5,650.00	75.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	64,326.95	6,800.00	57,526.95	89.43
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	64,326.95	5,400.00	58,926.95	91.61
+ GST 8.00/8.00% (S\$)	5,146.16	432.00	4,714.16	91.61
Nett Amount (S\$)	69,473.11	5,832.00	63,641.11	91.61

INSPECTION

Date of Assignment:	31/01/2023		AP Automotive Services Pte Ltd
Date Inspected:	01/02/2023	Inspected At:	9006 Tampines St 93 #01-202 Tampines Industrial Park A Singapore 528840
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2023)
Parts:	143	ASTON MARTIN VANQUISH 5.9 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EM2121T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY SIDE PANEL LH	Repair	23,000.00 FL	*- FL
2	1		*REAR FENDER INNER PILLAR LH	Not Necessary	525.00 FL	*- FL
3	1		*REAR FENDER INNER PILLAR OUTER LH	Not Necessary	515.00 FL	*- FL
4	1		*REAR FENDER FLOOR PANEL LH	Not Necessary	480.00 FL	*- FL
5	1		*ROCKER PANEL SIDE SKIRT LH	Cracked	3,000.00 FL	*1,800.00 FL
6	1		*ROCKER PANEL SIDE SKIRT LOWER GARNISH LH	Distorted	2,200.00 FL	*1,200.00 FL
7	1		*REAR FENDER INNER COWLING LH	Not Necessary	860.00 FL	*- FL
8	1		*REAR KNUCKLE LH	Not Necessary	1,100.00 FL	*- FL
9	1		*REAR KNUCK ARM HUB WITH BEARING	Not Necessary	1,800.00 FL	*- FL
10	1		*REAR CONTROL ARM LH	Not Necessary	1,650.00 FL	*- FL
11	1		*REAR UPPER ARM LH	Not Necessary	1,700.00 FL	*- FL
12	1		*REAR TOE ARM LH	Not Necessary	800.00 FL	*- FL
13	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	771.00 FL	*- FL
14	1		*REAR SPORT RIM LH	Dented	15,000.00 FL	*2,000.00 FL
15	2		*REAR DOOR HINGE LH	Not Necessary	190.00 FL	*- FL
16	1		*REAR DOOR CHECKER LH	Not Necessary	129.00 FL	*- FL
17	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	220.00 FL	*- FL
18	1		*REAR DOOR INNER WEATHERSTRIP LH	Not Necessary	220.00 FL	*- FL
19	1		*REAR FENDER LH	Repair	986.00 FL	*- FL
20	1		*REAR FENDER INNER TRIM LH	Not Necessary	330.00 FL	*- FL
21	1		*REAR FENDER COWLING LH	Not Necessary	55.00 FL	*- FL
22	1		*REAR ABSORBER LH	Not Necessary	298.00 FL	*- FL
23	1		*REAR KNUCKLE BEARING LH	Not Necessary	961.00 FL	*- FL
24	1		*REAR BEARING HUB LH	Not Necessary	491.00 FL	*- FL
25	20		*BODY PANEL RIVET	Necessary	250.00 FS	*50.00 FS
26	5		*EXTERNAL FENDER CLIP	Necessary	320.00 FS	*50.00 FS
27	5		*REAR FENDER COWLING CLIP	Not Necessary	280.00 FS	*- FS
28	3		*CONTROL ARM BOLT	Not Necessary	60.00 FS	*- FS
29	3		*REAR UPPER ARM BOLT	Not Necessary	60.00 FS	*- FS
30	2		*REAR TOE ARM BOLT	Not Necessary	40.00 FS	*- FS
31	1		*REAR TYRE LH	Not Necessary	1,200.00 FS	*- FS
32	1		*BODY SEALANT	Necessary	200.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	59,691.00	5,200.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	2,864.05	250.00
Total Parts (\$\$)	56,826.95	4,950.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	3,000.00	800.00
2	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	800.00
3	TO RNR INNER TRIMS AND UPHOLSTERY TO FACILITATE REPAIRS	New	800.00	0.00
4	TO CHECK WATER LEAK	New	200.00	100.00
5	TO APPLY RUST PROOFING	New	300.00	50.00
6	COMPUTERISED 4 WHEEL ALIGNMENT	New	300.00	100.00
7	REMOVE AND REFIT REAR UNDERCARRIAGE	New	800.00	0.00
8	COMPUTERISED WHEEL BALANCING	New	300.00	0.00
Gross Labour Cost (S\$)			7,500.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >