



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 380X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL LAMP LH	SCRATCHED	399.00	399.00
1	REAR BUMPER	SCRATCHED	494.00	494.00
2	REAR BUMPER SIDE RETAINER LH/RH	NOT NECESSARY	68.00	-
1	REAR BUMPER REFLECTOR LH	SCRATCHED	49.00	49.00
1	SET REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR BUMPER LOWER GARNISH	SCRATCHED	299.00	250.00
	LESS 20% DISCOUNT		-267.80	-244.40
			1,071.20	977.60
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SCRATCHED	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEAT REAR FRAME MEMBERS. TO REMOVE AND REFIT ABOVE PARTS.		300.00	200.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH REAR AFFECTED AREAS.		400.00	200.00
	TO RUST PROOF AFFECTED REAR AREAS.	NOT NECESSARY	30.00	-
	TO CHECK AND RECTIFY WIRING SYSTEM.		40.00	30.00
			770.00	430.00
GRAND TOTAL			2,041.20	1,607.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,300.00

Report Ref No. CS/INC23000955/Svp3m4

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.