Auto 101 LLP



No. 2 Yishun Industrial St 1 Northpoint Bizhub, #02-01 Singapore 768159 Tel: 67545101

DATE: 10-2-2023

REPAIR ESTIMATE

VEHICLE:	SKX 380 X
MODEL:	Hyundai Elantra

/n	Description of part	Qty	Qty	
1	Tail lamp LH ScC	1	399.00	
2	Rear bumper SCC/? BT	1	494.00	
3	Rear bumper side retainer LH/RA X (V/V)	2	68.00	
4	Rear bumper reflector LH 5	1	49.00	/
5	Rear bumper clip - set NCC /	1 .	30.00	
6	Rear bumper lower garnish 3c/ Br	1	299.00	1222
•	Real camper tower Samuel	Sub-total 1	1,339.00	
	less	20% discount	1,004.25	244.4
7	Reverse sensor & C	Sub-total 2	200.00	
7	Reverse sensor & ~ /	1	200.00	/
		Parts total	1,204.25	
	Labour			0.4-1
8	To straighten and panel beat rear frame members. To remove and refit above parts.			200
9	To putty, re-spray painting and polish rear affected areas.		400.00	
10	To rust proof affected rear areas.		Annual Control of the	XNN
11	To check and rectify wiring system		40.00	30
11	10 011011	Labour total	770.00	
	Dowt and	Labour total	1,974.25	1607.

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

3 days L/5 = 321.52 = 1286.08 = 1300 gr

www.auto101.com.sg