

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

## **ESTIMATE FOR SGK4896P**

Mr Kum

27 Yishun St 51 #09-16 Signature@Yishun Singapore 768088

Mobile: +6596778495

Vehicle & Document Information

WIP No 62573

Reg No/Reg Date SGK4896P / 31/05/2018

Date In/Mileage

Chassis No WDC1569422J501556

Engine No 27091031611450

Make/Model MB/MB GLA 180 (X156) "FACELIFT"

Colour/Trim 021 149 Polar White/ 043 381 ARTICO Mari

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	26/01/2023/ 14:27	YK	395 / Yik Chan	Ное			
		Description of Goo	ds / Services		* Qty	/ Unit	Price Disc%	Amount
DRIVE IN	D/ACC DATE /EXCESS	E: 11396998 // 24/01 : TOW IN 25/01/2023		NO INDIA INT'L	AL T	AX	INV	OICE
BY/AUTHR S BPNSUB	DATE SURVE IZED ON NT NO PLAT	:			TIT	E		mis 60.00
PANEL BE BODY PAN A BPIRES	ELS WITH F	REPAIR AFFECTED AREAS REFINISH RONT BUMPER, LEFT FRO	1_3	MYMIT	7 11			4800 6000.00
LEFT REAL A BPILAB USING XE	R FENDER,	LEFT ROCKER PANEL, I	EFT 'B' PI	LLAR,			0.10	380.00
A BPILAB		TH FOCUS ADJUSTMENT.		HECK COOLING SYSTEM			0.07	7 120.00
A BPILAB REMOVE A		1 WITH RE-GAS. NETT	ANSMISSION	ASSY AND ELECTRONICS	S	f	hoto?	1970 2400.00
A BPILAB REMOVE UI		AGE FROM VEHICLE FOR	THE REPLAC	EMENT OF COMPONENTS			planto.	1920 2400.00
A BPILAB		OPTICAL WHEEL ALIGNM CELETTE BENCH TO COND		S & STRUCTURE		f	July 0.07	2 1000.00
Confirmed &	accepted by		19	-0	Jan	fun,	97495	7-19
Authorized	anator, and	company stamp 6773 353	ik Chan Ho Carriage Indust Care & Repair Care & Repair	ries Pte Ltd r Center 09 Fax: 6872 1272 carries contres	plp!	Resums	1238 3.	122-24d
Authorized SI	gnatory and	company statup 6777	Las Tales	William and the second	+	1411110	O Vilania	2.6

Validity of this estimate is 1d days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

## **ESTIMATE FOR SGK4896P**

Mr Kum

27 Yishun St 51 #09-16 Signature@Yishun Singapore 768088

Mobile: +6596778495

Vehicle & Document Information

WIP No 62573

Reg No/Reg Date SGK4896P / 31/05/2018

Date In/Mileage / 0

Chassis No WDC1569422J501556

Engine No 27091031611450

Make/Model MB/MB GLA 180 (X156) "FACELIFT"

Colour/Trim 021 149 Polar White/ 043 381 ARTICO Mari

1.00 1.00 1.00 1.00 1.00 1.00 1.00	2696.36 1444.89 68.61 141.08 1014.67 165.87 169.95	00.00 00.00 00.00 00.00 00.00 00.00 00.00	180.0 180.0 120.0 120.0 120.0 144.1 144.1 1014.1 1014.1 165.1 169.5
1.00 1.00 1.00 1.00 1.00 1.00 1.00	2696.36 1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00 00.00 00.00	960.0 960.0 180.0 120.0 120.0 1444.8 144
1.00 1.00 1.00 1.00 1.00 1.00 1.00	2696.36 1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00 00.00 00.00	960.0 960.0 180.0 120.0 120.0 1444.8 144
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	180.0 180.0 120.0 120.0 1444.8 1446.8 14
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	180.0 180.0 120.0 120.0 1444.8 1446.8 14
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	180.0 120.0 12696.3 1444.8 08.6 141.0 1014.6 165.8
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	180.0 120.0 12696.3 1444.8 08.6 141.0 1014.6 165.8
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	2696. 1444.8 uer 68.6 m. 5 141.0 4 1014.6 H 165.8
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	2696. 1444.8 uer 68.6 m. 5 141.0 4 1014.6 H 165.8
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	2696. 1444.8 uer 68.6 m. 5 141.0 uer 1014.6 H 165.8
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	2696. 1444.8 uer 68.6 m. 5 141.0 uer 1014.6 H 165.8
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	1444.8 68.6 141.0 1014.6 165.8
1.00 1.00 1.00 1.00 1.00	1444.89 68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00 00.00	1444.8 68.6 141.0 1014.6 165.8
1.00 1.00 1.00 1.00	68.61 141.08 1014.67 165.87	00.00 00.00 00.00 00.00	1014.6 1014.6 165.8
1.00 1.00 1.00 1.00	141.08 1014.67 165.87	00.00 00.00 00.00	1014.6 H 165.8
1.00 1.00 1.00	1014.67 165.87	00.00	H 1014.6
1.00 1.00	165.87	00.00	H- 165.8
1.00			
			I Iny
1.00	83.56		mi> 83.5
1.00	66.72		66.7
			de 181.6
			de 411.5
			205.4
			ney 47.1
1.00			de 161.
1.00	243.46	00.00	7 243.4
1.00	1605.92	00.00	bt 1605.9
1.00	40.65	00.00	NY 40.6
1.00	88.27		88.2
1.00			336.1
			237.8
			ary 237.8
		700	art 447.1
1.00	132.88	00.00	132.8
	1.00 1.00 1.00 6.00 1.00 1.00 1.00 1.00	1.00 181.67 1.00 411.52 1.00 205.45 6.00 7.85 1.00 161.72 1.00 243.46 1.00 1605.92 1.00 40.65 1.00 88.27 1.00 336.13 1.00 237.84 1.00 237.84 1.00 447.15	1.00     181.67     00.00       1.00     411.52     00.00       1.00     205.45     00.00       6.00     7.85     00.00       1.00     161.72     00.00       1.00     243.46     00.00       1.00     40.65     00.00       1.00     40.65     00.00       1.00     336.13     00.00       1.00     237.84     00.00       1.00     237.84     00.00       1.00     447.15     00.00

Confirmed & accepted by

Authorized signatory and company stamp are 8. Repair Center 4872 1272

Validity of this estimate is 14 days from date of grate. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST www.unuld mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel. 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





ESTIMATE FOR SGK4896P

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Kum

27 Yishun St 51 #09-16 Signature@Yishun Singapore 768088

Mobile: +6596778495

Vehicle & Document Information

WIP No 62573

Reg No/Reg Date SGK4896P / 31/05/2018

Date In/Mileage

Engine No

Chassis No

WDC1569422J501556

27091031611450

0 0

Make/Model MB/MB GLA 180 (X156) "FACELIFT"

Colour/Trim 021 149 Polar White/ 043 381 ARTICO Mari

Account No Date/Time Printed Terms CSE Operator CSM00128 Cash 26/01/2023/ 14:27 YK 395 / Yik Chan Hoe Description of Goods / Services Qty Unit Price Disc% Amount M RADIATOR GRILLE MERCEDES STAR CARRIER 1.00 82.12 00.00 82.12 RADIATOR GRILLE MERCEDES STAR 1.00 145.89 00.00 145.89 M FRONT CPA RADAR SENSOR 1.00 00.00 1233.72 1233.72 FRONT CPA RADAR SENSOR FIXTURE М 1.00 50.26 00.00 50.26 FRONT SUPPORT PANEL 1.00 1080.64 00.00 1080.64 М FRONT CROSS MEMBER 1.00 353.78 00.00 353.78 RIGHT FRONT CROSS MEMBER ABSORBER 1.00 173.41 00.00 173.41 M FRONT LOWER SUPPORT PANEL 1.00 472.78 00.00 472.78 A/C REFRIGERANT CONDENSER M 1.00 1185.38 00.00 1185.38 RADIATOR 1.00 916.69 00.00 916.69 M RADIATOR FAN BLOWER 1.00 524.61 00.00 524.61 RADIATOR LOWER AIR DUCT M 1.00 68.80 00.00 68.80 M RIGHT RADIATOR AIR DUCT 1.00 21.36 00.00 21.36 М RIGHT RADIATOR BOTTOM BRACKET 35.81 1.00 00.00 35.81 AIR INTERCOOLER 1.00 937.86 00.00 937.86 LEFT FRONT DOOR 1.00 2111.02 00.00 2111.02 M LEFT FRONT DOOR W/STRIP 1.00 317.72 00.00 317.72 M LEFT FRONT DOOR INSULATION 1.00 74.42 00.00 74.42 M LEFT FRONT DOOR WINDOW GUIDE RAIL ney- 144.50 1.00 144.50 00.00 M LEFT REAR DOOR 1.00 2274.37 00.00 2274.37 LEFT REAR DOOR W/STRIP 317.72 1.00 00.00 ny. 317.72 M LEFT REAR DOOR INSULATION no 1.00 74.42 00.00 74.42 noc-M LEFT REAR DOOR GUARD PLATE 1.00 33.05 00.00 33.05 ny M LEFT REAR DOOR WINDOW GUIDE RAIL 1.00 183.14 00.00 183.14 M LEFT REAR FENDER TRIM GARNISH 1.00 262.62 00.00 262.62 LEFT ROCKER PANEL M 1.00 1394.78 00.00 1394.78 LKK Auto Consultants hence notify LEFT RUNNING BOARD Ni 1.00 380.96 00.00 380.96 the Repairer of the following: M TS TWO-COMPONENT ADHESIVE ner - 904.72 1.00 904.72 00.00 To resurvey before/after spray painting M UNDERBODY PROTECTION WAX 1.00 116.39 00.00 116.39 To display damaged part(s) during resurvey M SEAM SEAL 1.00 116.42 116.42 00.00 Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from insurance Confirmed & accepted by Cycle & Carriage inhalige enter
Body Care & Reputer enter
Body Care & Nett 51.678.67 8% GST on 51678.67 4134.29

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

**Total Payable** 



Authorized signatory and company stamp

55,812.96