

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | | |
|--------------------------|--|--|----------------|-------|-------------------------|--|
| | INCOME INSURAI | NCE LTD | | Ref: | CS/INC23000960/Twp3e2 | |
| | 75 BRAS BASAH I INCOME CENTRE | ROAD SINGAPORE 189557 | | Date: | 17/04/2023 | |
| | ATTN: CYNTHIA A | NG | | Code: | INC | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | FBC 7319X | Veh. Inspected | d | SNB 1883K | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | MT/1206560-002 | Excess (\$) | | 0.00 | |
| | Assign From | HAZALYSA BINTE IBRAHIM | Assign Date | | 31/01/2023 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA VEZEL HYBRID | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2017 | |
| | Chassis No. | RU31253369 | Colour | | SILVER | |
| | Odometer | 124420 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. | Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/60 R16 | DUNLOP | | 6 mm | |
| | L/H Front Tyre | 215/60 R16 | DUNLOP | | 6 mm | |
| | R/H Rear Tyre | 215/60 R16 | DUNLOP | | 6 mm | |
| | L/H Rear Tyre | 215/60 R16 | DUNLOP | | 6 mm | |
| 4. | | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | | |
| 5. | | General Information | | | | |
| | Accident Date | 23/01/2023 | Inspect Date / | Time | 31/01/2023 (03:47 PM) | |
| | Survey held at | MY CAR CONSULTANT PTE LTD | | | | |
| | | 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869 | | | | |
| 5a. | | Remarks | | | | |
| | | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | | Estimate Days of Repair | | | | |
| | ESTIMATED NOR | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |
| | | | · | | <u> </u> | |