

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 6027Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>LABOUR</u>			
	TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS: - NS REAR ENGINE DOOR PANEL - NS REAR SIDE SMALL PANEL - NS REAR AIR FILTER ACCESS DOOR		3,250.00	1,300.00
	SPRAY PAINTING: - NS REAR ENGINE DOOR PANEL - NS REAR SIDE SMALL PANEL - NS REAR AIR FILTER ACCESS DOOR		1,920.00	1,280.00
			5,170.00	2,580.00
	GRAND TOTAL		5,170.00	2,580.00

RECOMMENDED COST OF REPAIRS 2,580.00

Report Ref No. CS/FCI23000961/Rqp3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.