



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 6414J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	1,495.00	1,285.60
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	421.00	-
1	REAR BUMPER SPONGE	CRACKED	168.00	168.00
1	REAR END PANEL IMMOBILIZER ANTENNA (ADDITIONAL)	SHORTED	425.80	371.50
	LESS 25% DISCOUNT		-627.45	-456.28
			1,882.35	1,368.82
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER SENSOR (SN)	SHORTED	280.00	200.00
10	REAR BUMPER CLIP @\$5.50 (SN)	NECESSARY	55.00	55.00
1	REAR LOWER BUMPER SET (ACCESSORY) BODYKIT (SN)	CRACKED	2,800.00	1,500.00
			3,135.00	1,755.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT DAMAGE PARTS TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		1,200.00	250.00
	TO SPRAY PAINT DAMAGE PARTS.		900.00	400.00
	CHECK WIRING.		80.00	15.00
	ANTI-RUST.	NOT NECESSARY	80.00	-
			2,260.00	665.00
	GRAND TOTAL		7,277.35	3,788.82
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,000.00

Report Ref No. CS/INC23000969/Kwp3m4

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.