



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC23000969/Kwp3m4

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 22/05/2023

ATTN: JEFF LIN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBN 6563E	Veh. Inspected	SKU 6414J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1207797-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	31/01/2023

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER (A)	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	AVU650024447	Colour	M. P. WHITE
Odometer	165606 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/45 R19	MICHELIN	8 mm
L/H Front Tyre	245/45 R19	MICHELIN	8 mm
R/H Rear Tyre	245/45 R19	MICHELIN	8 mm
L/H Rear Tyre	245/45 R19	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/01/2023	Inspect Date / Time	03/02/2023 (11:30 AM)
Survey held at	COMPLETE VMS PTE LTD BLK 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**