

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC23000975/Tvp3m4	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557		Date	: 10/04/2023	
	ATTN: KENNETH I	НО	Code	e: INC	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLG 7673H	Veh. Inspected	SNC 819Z	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1206885-002	Excess (\$)	0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	31/01/2023	
2.	. Vehicle Particulars & Condition				
	Make & Model	TOYOTA NOAH	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	ZWR800504928	Colour	SILVER	
	Odometer	96619 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65R15	DAVANTI	6 mm	
	L/H Front Tyre	195/65R15	DAVANTI	6 mm	
	R/H Rear Tyre	195/65R15	DAVANTI	6 mm	
	L/H Rear Tyre	195/65R15	DAVANTI	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR O/S PORTION.			
5.	5. General Information				
	Accident Date	25/01/2023	Inspect Date / Time	31/01/2023 (02:43 PM)	
	Survey held at	KUM CHEW MOTOR WORKSHOP			
		160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722			
5a.	5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/INC23000975/Tvp3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser