3/27/23, 9:46 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS23000983/KWP3Q2

27/03/2023 Date:

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No:

**Claimant Vehicle** SMZ894X Insured Vehicle No: SDN9929R

No:

Date of Loss: 24/01/2023 Nature of Claim: ΤP Claim No: 2023 32004820SL

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMZ894X

ADIVA AD1 200, 190cc 3W M20AV289671 Make & Model: Engine No:

Reg. Date: 09/04/2021 (Man. Year: 2021) Chassis No: JTMY43FV00D517478

Colour: Metallic Grey Odometer: 65320 km

**Engine Capacity:** 1987 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/60 R18 225/60 R18 Rear Tyre Size: Front Left Side: Bridgestone 2 mm Rear Left Side: Bridgestone 2 mm Front Right Side: Bridgestone 2 mm Rear Right Side: Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		12,901.87	4,582.52	8,319.35	64.48
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,040.00	990.00	1,050.00	51.47
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	14,941.87	5,572.52	9,369.35	62.71
	Approved Total (Overridden) (S\$)		4,450.00		
	Nett Amount (S\$)	14,941.87	4,450.00	10,491.87	70.22
	Global Sum	Settlement (S\$)	0.00		

**INSPECTION** 

Date of Assignment: 31/01/2023

Em Solution Pte Ltd (160 Sin Ming) (HQ) Date Inspected: 31/01/2023 Inspected At:

160 Sin Ming Drive, #03-19 Sin Ming Autocity

Singapore 575722

Estimated Period of Repair: 4.0 days

XinYu Adjuster: **KENNETH KONG** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Mar 2023)

Parts: N/A ADIVA AD1 200 190cc 3W (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ894X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER -TOP	Buckled / Distorted	914.10 FL	*726.10 FL
2	1		*FRONT BUMPER -LOWER	Serviceable	756.30 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP -LH	Serviceable	371.50 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER	Serviceable	141.20 FL	*- FL
5	1		*FRONT BUMPER LOGO	Serviceable	121.60 FL	*- FL
6	2		*FRONT BUMPER SIDE RETAINERS -L/R	Serviceable	179.90 FL	*- FL
7	1		*FRONT FENDER -LH	Repair	1,035.70 FL	*- FL
8	1		*FRONT FENDER PROTECTOR	Dented	431.90 FL	*362.80 FL
9	1		*FRONT SPORT WHEEL -LH	Dented / Warped	1,755.60 FL	*1,551.80 FL
10	1		*FRONT SHOCK ABSORBER -LH	Bent	581.90 FL	*581.90 FL
11	1		*FRONT SHOCK ABSORBER TOP MOUNT	Bent	210.53 FL	*210.53 FL
12	1		*FRONT LOWER ARM	Distorted	790.65 FL	*790.65 FL
13	1		*FRONT LOWER ARM BALL JOINT	Bent	281.35 FL	*281.35 FL
14	1		*FRONT KNUCKLE ARM	Bent	731.50 FL	*681.20 FL
15	1		*FRONT WHEEL HUB	Bent	421.60 FL	*421.60 FL
16	1		*FRONT WHEEL BEARING	Necessary	210.50 FL	*210.50 FL
17	1		*FRONT DRIVE SHAFT -LH	Repair	1,459.63 FL	*- FL
18	1		*FRONT ANTI ROLL BAR	Serviceable	421.10 FL	*- FL
19	1		*FRONT ANTI ROLL BAR LINK	Serviceable	141.60 FL	*- FL
20	1		*FRONT STEERING RACK	Bent	1,954.90 FL	*231.60 FL
21	1		*FRONT HEADLAMP -LH	Serviceable	3,536.10 FL	*- FL
22	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
23	1		*FRONT TYRE -LH	Serviceable	350.00 FS	*- FS
24	1		*TIN AUTO TX OIL	Not Necessary	120.00 FS	*-FS
25	1		*BOT BRAKE FLUID	Not Necessary	50.00 FS	*- FS
F=Fra	ınchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	17,014.16	6,095.03
	- List Item Discount on L Items 25.00/25.00% (S\$)			4,112.29	1,512.51	
				Total Parts (S\$)	12,901.87	4,582.52

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO CHECK FRONT UNDERCARRIAGE	New	600.00	200.00
2	TO CHECK WHEEL ALIGNMENT	New	120.00	60.00
3	TO PRESS NEW WHEEL BEARING	New	120.00	30.00
4	TO RESPRAY PAINTING AND ETC	New	600.00	400.00
5	PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS	New	600.00	300.00
	Gross Labour	Cost (S\$)	2,040.00	990.00
	Report was unsubmitted during this p	print-out		

< END OF ESTIMATES >