

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|--|--|-----------------|-----------------------|--|
| | AUTOMOTIVE EN | GRG. & MGT. DIVISION (TP) | Ref: | CS/SPF23000984/Anp3e2 | |
| | FORCE) POLICE L | S SECTION (SPORE POLICE OGISTICS BASE (PLB) 1 SINGAPORE 438675 | Date: | 12/07/2023 | |
| | ATTN: HAFIZUL FA | ARHAN BIN RAHMAT | Code: | SPF | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | GBC 5839A | Veh. Inspected | SMN 7022M | |
| | Policy No. | | Coverage (\$) | 0.00 | |
| | Claim No. | ACS/105/009/2023/004 | Excess (\$) | 0.00 | |
| | Assign From | HAFIZUL FARHAN BIN RAHMAT | Assign Date | 31/01/2023 | |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | AUDI Q2 | c.c | 999 | |
| | Engine No. | HIDDEN | Year of Reg. | 2019 | |
| | Chassis No. | WAUZZZGA7KA056950 | Colour | ORANGE | |
| | Odometer | 35497 KM | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | SPORTS RIM | |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 215/55 R17 | BRIDGESTONE | 6 mm | |
| | L/H Front Tyre | 215/55 R17 | BRIDGESTONE | 6 mm | |
| | R/H Rear Tyre | 215/55 R17 | BRIDGESTONE | 6 mm | |
| | L/H Rear Tyre | 215/55 R17 | BRIDGESTONE | 6 mm | |
| 4. | 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 28/01/2023 | Inspection Date | 01/03/2023 | |
| | Survey held at | PREMIUM AUTOMOBILES PTE | LTD | | |
| | | 55 UBI ROAD 1 . SINGAPORE 408699 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days | | | | |